Quality Control Check Repot. Stage: After Plastering (Apartments)

Flat No.	5	Other		SI. No.	27.20
)	i d				0000
Company	VICTA HOMES	Project	UISTA HOMES	Phase	•
Prepared by	S. Eulderp	Sign	Dudup	Date	29 06 2018
Project Manager	T. Madha	Sign	7 why	Date	29 06 2018
Previous stage report no.	0.	29981	Report filed and signed by PM?	d by PM?	✓ Yes □No
Checked By MD on	7, 77	MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	commendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after submit Proceed with further work only after making of Proceed with further work. ATR not required	port to QC team. Procestr submitting ATR on ing corrections pointed ired.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck b Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. A Proceed with further work. ATR not required.	y QC. ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark **XX** for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

		Ren	15	14	13	12	11	10	9	8	7	6	2	4	ω	2	-	S No
3) Plantuin	2) (2,	Remarks り パー	Other	Other	Kitchen	Utility/balcony-3-	Utility/balcony 2	Utility / baleony-1-	Lebby-l-	Dining	Drawing	Foilet 3	13		n 2	Toilet I	n 1	Room
1,33	s resate	7.5				4	2	宁					G ·8	-1	B. 3	<u>۲</u>	(n.B	
30	Ten c	Finishia			<	(1	1	1	1	1	}.	1	1	?	4	4	Skirting Provision (v or x)
5	borna	2.			4	1	1	1	1	ζ	(Ī	J	1	7	<	7	Finishing around door frame (• or ×)
n) plc	e bres	Maplu			1	Ţ	<	1	1	(1	1	~	1	/	(9	Beams & columns finishing (v or x)
daus		5 (9)			1		1	1		1	1	ŧ	1	1	1	t	•	Finishing of lofts (v or x)
ngt done:	>	common toilet			<		<	1	ļ	٢	1	1	1	((<	/	Electrical junctions finishing (• or ×)
one.	C.	1			\	ļ	1	1	-	1	١		1	. 1	(1	1	Window check ⁶ (✓ or X)
	tud	not don			1		Ī	~	1]	1		1		1	\	1	Tiles provision (✓ or X)
	•	E			1	ļ	-	1	1	١	Ţ	•	-	Ţ	1	1	1	Sink provision & size (or x)
					ţ	Ì	1	1	-	1	1		~	V	<	./	1	Grooves for door frames (• or ×)
					1	1	Ì	1	1	Ĭ	1		1	Ţ	Į	ţ	ı	Balcony & terrace sill top finishing(v or x)
					1	1	1	1	1		1	1		<	1	1	•	Screeding in bathroom & utility (v or x)
					1	1	1	1)	1	•]	1	1	1	<	1	Screeding in 6" above FFL? (v or x)