## Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Recommendation	Flat No.  Company  Prepared by  Project Manager  Previous stage report no.  Additions & alterations s  Checked By MD on  Programmendation:	telp had	Other Project Sign Sign Sign MD Sign	SI. No.  Wister Horres Phase  Shelfer Date  Report filed and signed by PM?  All pages signed by engineer &	Sl. No.  Phase  Date  Date  d by PM?  ngineer & customer?  For filling	31015  31 04 /2018  31 04 /2018  Yes \( \) No
ons sheet date  Unler de de de la pages signed by engineer & customer?  MD Sign  For filling	Previous stage report	t no.	00+08	Report filed and signe	d by PM?	ΣΥes
MD Sign For filling	Additions & alteratic	ns sheet date	antold	All pages signed by er		☐ Yes
	Checked By MD on	U)	MD Sign			☐ Yes

Inspection should be done after:

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

## After Plumbing & Electrical Check.

## Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark **XXX** for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance I".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- 10. Height of DB box must be 6" below false ceiling level or 12" below slab level
- 11. In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

## Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

۲	Si	R		Re	15	14	13	12	11	10	9	8	7	6	5	4	Ş	2	<b></b>	S No	
Revised drawing required from HO	Signed by engineer,	Remarks on additions & alteration sheet:		Remarks	Other	Other	Kitchen	Utility/balcony3	Utility / balcony 2 -	Hility/balcony 1	Ьоbby I-	Dining	Drawing	Teilet 3—	Bedroom 3	Toilet 2	Bedroom 2	Toilet 1	Bedroom 1	Room	Trio.
required	er,	ions &						on <del>y 3</del>	ony 2 -	ony 1	23					(८ न)	(B.X)	(3.1)	(an)		•
from HO		ilteration sheet:					Ţ	-	(	7	1		į		<b>B</b>	Ţ	1	1		balcony & utility ( • or ×)	Civil work near pipes in
]Yes □No	☐ Yes ☐ No	uneold		The state of the s			<	1	ζ	1	-	1	1	1		ζ	1	7	1	( v or x)	PVC Check
Appro	Signed	ted that.					<		(	7		1	<	1	1	(	7	۲	5	( • or ×)	Electrical points check
Approved revised drawing attached	Signed by customer,	•						1	(			1	(	ļ	4	<	1	(	-	check ( or	proofing
ving attached							1		1	1		(		9	1	1	1	1	1	check (v or	
Yes No	Yes No	1					1		1	-		1	ζ	1	1	1	•	1	1		DB ( • or ×)
	1						1	)	1	***	1	•	1			•	١	1	1	changeover (✓ or 🗙)	Generator of