Quality Control Check Repot. Stage: After Plastering (Apartments)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	Checked By MD on MD Sign For filling	Previous stage report no. 89985 Report filed and signed by PM?	Project Manager T. Modfill. Sign Mulling Date	Date	Company Visto Homes Project Visto Homes Phase	Flat No. D-105 Other SI No.
uired.	☐Yes ☐No	Yes No	02/7/18	C2) 1/(8		30703

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

	Rer	15	14	13	12	1	10	9	8	7	6	5	4	ပ	2	1	S No
	Remarks () Generator	Other	Other	Kitchen	Utility / balcony 3	Utility / balcony 2	* Utility /balcony 1	Lobby-1	Dining	Drawing		Bedroom 3 Gr-Bed	\cap	n 2	-	Bedroom 1 M. 8ed	Room
_	charge			/		(~	١	1	ς	1	ζ	ς	(٢	ς.	Skirting Provision (• or ×)
	O ON GY			ς.	1	<	1	ſ	١	<	1	<	٢	ζ	٢	1	Finishing around door frame (• or ×)
	y pox			ς .	1	ζ	(1	١	<	1	5	(5	ς	3	Beams & columns finishing (• or ×)
	TOOK			(1	1	1	1	1	1	1)	}	1)	3	Finishing of lofts (• or ×)
	Little !			ζ	ļ	5	١	1	1	K	1	<	5	<	ζ,	ζ	Electrical junctions finishing (v or X)
				1	1	1	ſ	1	ļ	1		1	1	!		}	Window check ⁶ (• or ×)
				ζ	1	ς.	1	1	1	١	1	1	5	1	5	ı	Tiles provision (v or x)
				١	1	1	1	1	1	1	1	١	1	1	1	1	Sink provision & size
				1	1	(. 1	1	1	1		<	<	<	ζ.	5	Grooves for door frames (✓ or X)
			ļ	1	1	ļ	ζ	1	1	1		1	1	7	1	1	Balcony & terrace sill top finishing(v or x)
				1	1	<	1	1		1			1	,	<	!	Screeding in bathroom & utility (v or x)
				1	1	<		, ,		١	(۱	١	,		7	, ,	Screeding in 6" above FFL? (• or ×)

Quality Control Check Repot. Stage: After Plastering (Apartments)