Quality Control Check Repot. Stage: After Plastering (Apartments)

Flat No. Company Prepared by Project Manager Previous stage report no. Checked By MD on Recommendation:	P-123 RMR-II M. Teja Svidher K SHIRISH no.	Other Project Sign Sign 있구되나	PARE Date Report filed and signed by PM?	Sl. No. Phase Date Date d by PM? For filling	No Ses ☐ No Act of the other of les ☐ No Other
Project Manager	HSIZIHS Y	Sign	AM	Date	41/80/40
Previous stage report 1	no.	44256	Report filed and signe	d by PM?	√Yes □ No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	scommendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after superfected with further work only after making a Proceed with further work. ATR not required.	eport to QC team. Procter submitting ATR on ting corrections pointed ired.	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	by QC. ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.