Quality Control Check Repot. Stage: After Plastering (Apartments)

Company Project Repared by Project Manager Project Pr	Flat No					
te te te te te cfilling C. not required.	A LUC LANG.	D-223	Other		Sl. No.	32364
te te te filling C. not required.	Company	Pmp	Project	Aub	Phase	=)
te / PM? / filling / C. not required.	Prepared by		Sign	Mudero	Date	14/12/18
PM? filling C. not required.	Project Manager		Sign	238	Date	14/12/18
filling [C.]	Previous stage report 1	no.	27635	Report filed and signe	d by PM?	∠Yes □No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
	Recommendation: Stop further work. Stop further work. Proceed with further	Submit ATR on QC-re Proceed with work aft er work only after maki er work. ATR not requi	port to QC team. Proceer submitting ATR on ing corrections pointed red.	eed only after recheck become to QC report to QC team.	y QC. ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed,
- before starting painting, tiling & flooring.

Plastering Check.

Notes:

- Mark \checkmark for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

T			Re	15	14	1.5	- 1 - 1	13	11	10	9	7	× ·	7	6	U	1	7	w	2	 	
			Remarks	-	-	+-	-	_	_	- 2	L	1		- 1	_		-	-	_	_	_	3 No
			ks	Other	Other	Kitchen	CATTONION / CATTONION	[Hillity / halland	Utility / balcony 2	Utility / balcony 1	obby I	Sumg	Dining)rawing	oilet 3	Bedroom 3		ţ	3	Toilet 1 my	Bedroom 1 m.B	Room
						1	 !	,		,	1	!	1		,	}	ς	7	,	1	7	Skirting Provision
					-	i	1	,		1)	-	7		!	1	ς.	<	7		۲	Finishing around door frame (v or x)
				+	-	ζ		7	,	<u> </u>	1	1	<			!	<u>ς</u>	5	`		7	Beams & columns finishing (• or ×)
						*	į			\ -	1	1	1			1	(ſ	1			Finishing of lofts (v or x)
					•		Į	(7	1	,	1	5	1	-		\	<	5	\	\	Electrical junctions finishing (v or x)
					*		!	7	1		¶	ļ	7		<u> </u>			٢	7	7		Window check ⁶ (✓ or 🗙)
					7		١	ĺ	7	1			1	ļ			1	1	<	!		Tiles provision (v or x)
			25	-	1			ļ —	1	i	-	0.0	1	1	1	, 	١	1	3	1		Sink provision & size
					[ζ.	1	1	 -	,	(1	K	,		7	1		Grooves for door frames (vor x)
					1		 	•	×	1	1		1		1	1		!	•	ı	I	Balcony & terrace sill op finishing(v or x)
					1	1	(\	Ī		1			!	1	!			•	L your	8	Screeding in bathroom & utility (v or x)
					1	!	7		1		1			1	1	Ī	1		,	1	S	Gereeding in 6" above FL? (v or x)