Quality Control Check Repot. Stage: After Brickwork (Apartments)

Flat No.	D-226	Others	X	Sl. No.	27632
Company	PMR	Project	PMR	Phase	-
Prepared by	M. Tega Stidher	Sign	To the state of th	Date	t1/40/38
Project Manager	K. SHIRISH	Sign	A.	Date	26/07/17
Previous stage report no.	no.	26792	Report filed and signed by PM?	ed by PM?	√Yes □No
Apartment No		Other		Other	
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	eport to QC team. Procter submitting ATR on sing corrections pointedired.	eed only after recheck QC report to QC team d out in the QC report.	by QC. ATR not required.	

Inspection should be done after:

- brickwork is completed
- chicken mesh fixed
- after cleaning the apartment
- electrical conducting work is completed

Brickwork Check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark **XX** for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- . Wall thickness should be as per plan. Use of 4", 6" & 8" blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- 7. Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- 0. Diagonals of each room shall be equal. (Tolerance: 2")
- . Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- 2. Check room height with specified height. (Tolerance: 1")
- 13. Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- 14. Specify the No. of beams which are not aligned by more than I"in a room.
- 15. Door frames must have black Japan coating and wood primer / pellambar at cost of painter.

Ren	15	14	13	12	=	Ξ	9	∞	7	6	5	4	ယ	2	}	S No
Remarks	Other	Other	Kitchen	Ntility-/_balcony-3-	Utility / baleony 2	Dillity / balcony 1	Lobby 1	Dining	Drawing	Toilet 3	Bedroom-3	Toilet 2 (Cc7)	Bedroom 2 (KB)	Toilet 1 (MT)	Bedroom 1 (MB)	Room
	ļ		<	1	<	۲,	•	۷	<	1]	<	<	<	<	Wall thickness (✓ or X)
			<	-	८	<	`	<	<	(ſ	~	5	<	<	Beds in walls (• or ×)
			<	1	۷,	<		<	<	[ſ	1	<	<	<	Chicken mesh
			<		<	≺.		<	<	Ţ	1	√	<	<	<	External brickwork & beam joint (• or ×)
			<	:	4	<		<	<	1	ţ	く	<	<	<	Room Dimensions (• or ×)
			\					19	ţ	-[J	(1	1	1	Room Dimensions Difference in inches
			<	1	۷,	<	8	<	<	1	}	1	<u> </u>	~	く	Diagonal (v or x)
			١	Ţ		0	-	•	[\	1	1		ī	1	Diagonal Difference in inches
			1	ı	4	!	1	ı	(ţ	1	1	1	1	ţ	Balcony sill level (▼ or ×)
			<	\	<	ζ	1	Z.	く	١	1	く	く	<	<	Room Height (✓ or X)
		(AVa	• [11	Ava	ſ	له س	Ava	1	}	11	11	11	Avq	Plumb of walls (Good/Avg./Bad)
			<	1	<	5	5	<	<	1	J	<	<	<	ζ	Alignment of beams and walls - Nos.

Drum (200 lts) provided for curing in each flat?
--

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XXX for major mistake that cannot be corrected. Mark $\times \times$ for major mistake that requires correction by replacement or re-fixing.
- Window template depth should be between 2 to 2 1/2" after plastering.
- Lentil level should be 7'3" from SFL & 7' from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32" or 33" from FFL and 35" or 36" from SFL.
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- 10. Provide single layer table brick at bottom of each door frame without threshold.

Ren	15	14	13	12	11	=	9	∞	7	6	5	4	3	2	1	S No
Remarks:	Other	Other	Kitchen	-Utility/balcony 3	Utility / balcony 2	Dtility / balcony 1	Lebby	Dining	Drawing	Toffet3	Bedroom-3	Toilet 2 (CT)	Bedroom 2 (K§)	Toilet 1 (MT)	Bedroom 1 (MB)	Room
			1	•	<	•	1	1	〈	1	ş	<	\	〈		Door size, face and position (✓ or X)
			1	1	١)	}	1	ţ	-	}	1	۷	١		Brick at bottom of door frame (✓ or 🗙)
			1	1	<	Į.	1	1	ς	/	{	<u>く</u>	<	<	<	Door lentil level (v or X)
			1	1	<	-	1	\	ζ	1	1	~	<	<	<	Door diagonal check
			1	1	<	ļ	j	1	<		١	4	3	4	<	Door Plumb - two sides
			١	1	<	١	}	1	<	1	ì	<	<	<	<	Door frame black Japan/ wood primer/Peelambar check (vor X)
			<	1	ĺ	}	1	ſ	ζ.	1	١	<	く	<	<	Windows lentil & sill level (✓ or X)
			\	1	1	1	1	1	<	1	1	<	〈	く	<	Windows size (✓ or 🗙)
			<	1	1	1	1	1	<	1	Y	<	۷	く	<	Windows - template depth & diagonal (✓ or X)
			<	ļ	1	ì	ļ	1	<	1	1	\	ς,	<		Windows - template powder coated (v or X)
			₹	1	١	1	1	1	J	j	1	1	1	1	1	Loft & Kitchen platform required ? (Yes or No)
100			1	1	1	9	1	1	1	Ì	ħ	\	١	j		Loft & Kitchen platform provided (v or X or NA)
			1	1	١	1	1	1	1	!	1	١	1	A. C.	1	Loft & Kitchen platform slope (✓ or ×)

Quality Control Check Repot. Stage: After Brickwork (Apartments)