Quality Control Check Repot. Stage: After Plastering (Apartments)

Company Prepared by	Vista Hames	Other Project Sign	Vista Homes	SI. No. Phase Date	3/207
Project Manager	e Lity Agelly Sign	Sign	XX	Date	20/08/19
Previous stage report no	Û	30829	Report filed and signed by PM?	ed by PM?	Yes No
Checked By MD on		MD Sign		For filling	Yes No
Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	port to QC team. Procest submitting ATR on ing corrections pointedired.	eed only after recheck QC report to QC team d out in the QC report.	by QC. 1. ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed,
- before starting painting, tiling & flooring.

Plastering Cheek.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing. Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering).
- Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 'a grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.