Quality Control Check Repot. Stage: After Brickwork (Apartments)

		The second of th			
Flat No.	P-401	Others	(1)	SI. No.	27513
Company	BNC	Project	MEG	Phase	
Prepared by	M. Teja Svidher	Sign	al	Date	n. Ladia
Project Manager		Sign	1 21	Date	4/150/ho
Previous stage report no.	no.	88988	Report filed and signed by PM?	d by PM?	NYes No
Apartment No		Other		Other	
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation:					
Stop further work.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC, Stop further work. Proceed with work after submitting ATR on QC report to QC team.	port to QC team. Proce	ed only after recheck l	by QC.	
Proceed with furthe	Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	ing corrections pointed ired.	out in the QC report.	ATR not required.	

Inspection should be done after:

- brickwork is completed
- chicken mesh fixed
- after cleaning the apartment
- electrical conducting work is completed

Brickwork Check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- . Mark **XXX** for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4", 6" & 8" blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- Diagonals of each room shall be equal. (Tolerance: 2")
- 1. Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- 12. Check room height with specified height. (Tolerance: 1")
- 3. Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- 4. Specify the No. of beams which are not aligned by more than 1"in a room.
- 15. Door frames must have black Japan coating and wood primer / pellambar at cost of painter.

	Ren	15	14	53	5	Ξ	10	9	8	7	6	5	4	3	2	1	S No
7 10	Remarks Note: Thure	Other	Other	Kitchen	Utility / bulcony 3	Utility / balcony ?	Utility / bulcony 1	Lohby 1	Dining	Drawing	Toilet3	Bedroom 3.(48)	Toilet 2 (cr)	Bedroom 2 (ks)	Toilet 1 (Mて)	Bedroom 1 (MB)	Room
at.	200			-	Ī	. •,	₹,		<	<	1	V	, ζ	<	<	<	Wall thickness (✓ or ×)
	Were			١,	i	1	Κ,	·	<	く	1	く	<	<	<	<	Beds in walls- (✓ or ×)
	Some				1	ľ.	<,	ť	<	<	1	<	<	<	<	<	Chicken mesh (✓ or X)
500	Customer	,		1		1	۷.	į	<	<	I	\	<	<	<	<	External brickwork & beam joint (or ×)
	ner (1		1	<u> </u>	9 1	<	<	1	<	<	<	~	<	Room Dimensions (• or ×)
0	hange			1)	1		!	١	1	1	(ſ	Ş	١	,	Room Dimensions Difference in inches
	one o			Į]		<	-	<	<	١	۷,	<	<	<	<	Diagonal (v or X)
	anding			1	1	[-	1)	\	((Ţ	1	ļ	Diagonal - Difference in inches
	9 the			1	1	1			1	ſ	١	1	ļ	}	W 1		Balcony sill level
				1)		く	Ì	<	<	\	<	<	<	<	<	Room Height (v or x)
The state of the s	diminoions			1)	ار	Ava	ļ	= \ - \	Ava	1		=		-1	Avg	Plumb of walls (Good/Avg./Bad)
	2			1]	1	1	1	<	<		<	۷	4	<	ζ	Alignment of beams and walls - Nos.

Quality Control Check Repot.

Stage: After Brickwork (Apartments)

Quality Control Check Repot. Stage: After Brickworl	Stage: After Brickwork (Apartments)
Quality of edges and corners in all rooms?	☐ Good ☑ Avg. ☐ Bad
Specify rooms that need correction:	
	Table (Calculate)

Misc. Checks.	
Was 3.75 CFT proportion box provided?	√Yes □ No
Condition of proportion box?	☐ Good ☑ Avg. ☐ Bad
Was the Apartment cleaned before starting brick work?	☐ Yes ☐ No ☑ Cant' say
Is the Apartment cleaned for plastering?	√Yes □No
Wastage?	☐ High Medium ☐ Low
Storage of building material like bricks sand and cement.	☐ Good ☑ Avg. ☐ Bad
Drum (200 lts) provided for curing in each flat?	\ \sqrt{\text{Y}}\text{es} \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \
Remarks:	

Door Frames & Windows check

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark X for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 ½"after plastering. Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32" or 33" from FFL and 35" or 36" from SFL. (Tolerance 1")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- 10. Provide single layer table brick at bottom of each door frame without threshold.

Re	15	14	13	12	=	10	Ç	∞	7	6	S	4	ယ	2	_	S No
Remarks:	Other	Other		Utility /	111111y /	lJulity /	I videlow I	Dining	Drawing	Foilet-3	Bedroom	Toilet 2	Bedroom 2	Toilet 1	Bedroom	Room
				balcony 3	balcony 2	buleony 1					3 (48)	(7)	2 (KB)	(MT)	1 (MB)	,
			1		ζ.			!	1	1	<	<	<	<		Door size, face and position (✓ or X)
			1		<	8	ď	(Ţ	f	~	1	<	١	<	Brick at bottom of door frame (✓ or ×)
			!	ě	<	1 2	×	١	ì	1	4	<	<	<	<	Door lentil level (• or ×)
			ſ	1	<_	¥ .	ā,	١	١	1	4	<	<	<	<	Door diagonal check
			Ĭ	ĺ	<	1	ī	١	}	1	〈	<	<	<	5	Door Plumb - two sides (✓ or 🗙)
			١	1	<	į	1	İ	}	1	<	<	<	ζ		Door frame black Japan/ wood primer/Peelambar check (vor X)
			A CONTRACTOR OF THE PARTY OF TH		(<u> </u>		/	1	ļ	<	٧,	<	<	<	Windows lentil & sill level (✓ or ×)
			*		[1	ļ	1]	-	<	<	<	<	<	Windows size (✓ or 🗙)
			3	1	1	1	1	1	j	-	<	<	<	<		Windows - template depth & diagonal (✓ or X)
			•	1)	ſ	1	1	1	i	<	<	<	<		Windows - template powder coated (✓ or 🗙)
			•		1	J	1	1)	1	(ſ	1	1		Loft & Kitchen platform required ? (Yes or No)
			1	١	1	1		1	J	1	1	}	}	١		Loft & Kitchen platform provided (• or × or NA)
			1		j	}		£	}	1	{	ĺ	İ	1		Loft & Kitchen platform slope (✓ or X)

Quality Control Check Repot.

Stage: After Brickwork (Apartments)