## Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Prepared by   Project   Project   Project   Project   Project Manager   Cobba Reddy   Sign   All   Date   OA (10   14   Project Manager   Cobba Reddy   Sign   All   Date   OA (10   14   Provious stage report no.   Q2+64   Report filed and signed by PM?   Date   OA (10   14   Provious stage report no.   Date   OA (10   14   Provious stage report no.   Additions & alterations sheet date   UASOLAF(Zt   All pages signed by engineer & customer?   Yes   No   Recommendation:   Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.   Stop further work only after making corrections pointed out in the QC report. ATR not required.   Proceed with further work. ATR not required.	Flat No.	F0S-9	Other		SI. No.	28163
Date  The port filed and signed by PM?  Report filed and signed by PM?  Sold Flat  All pages signed by engineer & customer?  Sign  For filling  to QC team. Proceed only after recheck by QC.  ubmitting ATR on QC report to QC team.  corrections pointed out in the QC report. ATR not required.	Company	BNC	Project		Phase	17
Date   Report filed and signed by PM?   Sold Flat   All pages signed by engineer & customer?   For filling   For filling   For filling   For filling   Corrections pointed out in the QC report. ATR not required.		M. Teja Sridhor	Sign	TE	Date	t1/01/t0
Report filed and signed by PM?  Sold F(X) All pages signed by engineer & customer?  Sign For filling  to QC team. Proceed only after recheck by QC.  ubmitting ATR on QC report to QC team.  corrections pointed out in the QC report. ATR not required.			Sign	12	Date	41/01/40
All pages signed by engineer & customer?  Sign For filling to QC team. Proceed only after recheck by QC.  ubmitting ATR on QC report to QC team.  corrections pointed out in the QC report. ATR not required.	Previous stage report no	0.	17248	Report filed and signe	d by PM?	XYes \( \square\) No
To QC team. Proceed only after recheck by QC. ubmitting ATR on QC report to QC team. corrections pointed out in the QC report. ATR not required.	Additions & alterations	sheet date	Unsold Flat	All pages signed by en	25.00	□Yes □No —
to QC team. Proceed only after recheck by Qubmitting ATR on QC report to QC team. corrections pointed out in the QC report. ATR	Checked By MD on		MD Sign		For filling	☐Yes ☐No
Inspection should be done after:	Recommendation:  Stop further work. S  Stop further work.  Proceed with further  Proceed with further  Inspection should be done af	Submit ATR on QC re Proceed with work aft r work only after mak r work. ATR not requi	port to QC team. Proceer submitting ATR on fing corrections pointed ired.	eed only after recheck b QC report to QC team. I out in the QC report. A	y QC.	

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request

## After Plumbing & Electrical Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1"
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

## Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Remarks on additions & alteration sheet:    Unsold Flat	Remarks	15 Other	14 Other		12 Utility t-baleony-3	11 Utility Lbalcony 2 \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	10 Litility + balcony 1	9 Foppla	8 Dining	7 Drawing		5 Bedroom-3	4 Toilet 2 (CT)	3 Bedroom 2 ( (以) — — — — — — — — — — — — — — — — — — —	2 Toilet 1 (NT)	(	near pipes in PVC Check points check proofing fasteners  balcony & (vor x) check (vor check (vor x))  near pipes in PVC Check points check (vor check (vor x))  No of utility (vor x)  x)
er, [				1		1			\	<b>j</b>		1	1	>		5	
Yes No				1		\		<b>\</b>		<	1	-	1	1	1	1	DB (v or x)
				1	1					\				1 1	•		Generator changeover ( • or ×)