Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Flat No.	D-601.	Other		Sl. No.	28107
Company	BNC	Project	スだ	Phase	1
Prepared by	M. Teja Sridhu Sign	Sign	7	Date	t1/60/80
Project Manager S	S. V-Subbaleddy Sign	Sign	1 Sh	Date	28/09/17
Previous stage report no.		28115	Report filed and signed by PM:	d by PM?	MYes □No
Additions & alterations sheet date	heet date	+1/40/20	All pages signed by engineer &	customer?	MYes □No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	ibmit ATR on QC re roceed with work aft work only after mak work. ATR not requi	port to QC team. Proce er submitting ATR on ing corrections pointed ired.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not Proceed with further work. ATR not required.	y QC. ATR not required.	

spection should be done after

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

After Plumbing & Electrical Check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark **XXX** for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- 10. Height of DB box must be 6" below false ceiling level or 12" below slab level.
- 11. In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

		Ö	OACH ICANSCO man		∐Yes ☑ No	ed from HO	Revised drawing required from HO	
	∏Yes □No	wing attached	A serviced drawing attached		11		Signed by engineer,	
	又Yes LINO		Signed by customer,		Was TINO		-	Γ-
					F;	alteration sheet	Remarks on additions & alteration sheet:	
								_
	1			Chandy a	Jenn	Thou are	0.50	
	Juguot.	whener				}		
		V (WO CENTEN	a as rev	not fined	Boards		Remarks Nothing Switch	
* .	, t	5		5			5 Other	
							4 Other	_
					1		3 Kitchen	_
	1	1	(f		•	2 - HHILLY - Balcony 3	_
							0	Ξ
		1	\	1	(ζ,		
1	1			1	1	٤,	⊃ - +	=
1	1		1		1	•	_	5
1	1	- 					Dining	00
			ſ	()	()		Drawing	7
<	<		1			1	Torlet 3	9
	١	1	ı		1		Bedroom 3	S
1		1		1 1			Toilet 2	4
	1	1	1			- Land	Bedroomz	S
1	1			\	1		Tollet 1 (MI)	2
			1	*	12/			-
	1	1	-	*	1	1	Redroom 1/MB)	-
1	١					×		SI
(or X)			X) .	(v or x)	(or x)	balcony & utility (• or	oom	No
Generator changeover	DB (v or x)	fasteners check (> or	proofing	points check	PVC Check	near pipes in		
Placement of	Placement of	Proper use of	Water	Flectrical	CDV/C &	2		
						>-		