Quality Control Check Repot. Stage: After Plastering (Apartments)

Recommendation: Stop further work. Stop further work. Proceed with further Proceed with further	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Flat No.
Stop further work. Submit ATR on QC report Stop further work. Proceed with work after some Proceed with further work only after making of Proceed with further work. ATR not required.	32	10.	S.V.S. ble Red Sign	P. Son tumor	BNC	D-602
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not proceed with further work. ATR not required.	MD Sign	98846	Sign	Sign	Project	Other
ced only after recheck l QC report to QC team l out in the QC report.	The state of the s	Report filed and signed by I	rell	- 42g	NFG	
ру QС. ATR not required.	For filling	d by PM?	Date	Date	Phase	SI. No.
	☐Yes ☐No	NYes □No	4-10-E	7/01/2	H	28192

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. <u>Plastering must be 3mm margin for luppum work</u>. Tolerance 1/2. Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

		Ren	15	14	13	12	=	10	9	8	7	6	5	4	ယ	2	1	S No
	X 06 × 0	Remarks	Other	Other	Kitchen	Utility/balcony 3	Uti lity / balcony 2	Utility / baleony 1	Lobbyi	Dining	Drawing	Toi let 3	Bedroom 3 as	Į	12	Toilet 1 № T	n 1	Room
	Colored	B)			<	Ţ	Х	7	1	<	<	1	V	ζ,		7	Х	Skirting Provision (v or x)
	استعاب م	Dado			{	3	1		1	(7	1	Z,	\	<u> </u>	<u> </u>	<	Finishing around doc frame (v or x)
_	.	o tiles			<	١,		<	J .		<		<	~	~	く	<	Beams & columns finishing (• or ×)
	the set				ſ	}	}	1	•	1)	1	(1	-	}	1	Finishing of lofts (v or x)
	elechize	JUDITE FOU			X	1		ζ	-	ς	<		X		X	〈	*	Electrical junctions finishing (v or x)
	1,6	56			<	1	1	1	Ţ	(V	•••	\sim	< s	\	< <	`	Window check ⁶ (• or ×)
C	Tunch). - -			XX	1	1	<	1	ſ	1			<	1	<	1	Tiles provision (v or x)
	metrons	teles			<	1]	<	1	<	ſ	1	(<	1	<	(Sink provision & size
	हो	<u>ک</u> م			1	1	}	<	1	ſ	<	1	<	<u> </u>		<	<	Grooves for door frames (• or ×)
	pe,	as D			}	1	<	}	١)	j	1	1	1)))	Balcony & terrace siltop finishing(v or x)
, ,	200	Dev (-)	(5	1	}	1	(-	<)	<		Screeding in bathroom & utility (v or x)
0	enty	specifs			1	1	1	<	Ī)	1]	<	}	<	1	Screeding in 6" above FFL? (• or ×)

Quality Control Check Repot. Stage: After Plastering (Apartments)