Quality Control Check Repot. Stage: After Plastering (Apartments)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Q Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Flat No.
commendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after some Proceed with further work only after making Proceed with further work. ATR not required			S-V-Subsi Reldy Sign	Pigo Kimar	BNC	D-604:
port to QC team. Proceed the submitting ATR on the corrections pointed ired.	MD Sign	27879	Sign	Sign	Project	Other
scommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR n Proceed with further work. ATR not required.		Report filed and signed by PM?	war	RAY	Mfa	
by QC. ATR not required.	For filling	ed by PM?	Date	Date	Phase	SI. No.
	☐ Yes ☐ No	Nes No	16/10/17	16 01 18	3	28220

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Ren	15	14	13	12	11	10	9	∞	7	6	5	4	ယ	2	1	S No
Remarks	Other	Other	Kitchen	Utility/balcony-3	Utility / balcony 2	Utility / baleeny-1	Lobby 1	Dining	Drawing	To ilet 3	13 G	Toilet 2 とて	Bedroom 2 トル	Toilet 1 べて	Bedroom 1 №13	Room
			<,	1	~	ζ.	}	\	<	}	/	5	<u> </u>	<	5	Skirting Provision (• or ×)
Electrical			,	1	ſ	<	1	}	<		\	< '	N	<	<	Finishing around doo frame (v or x)
7			<	.1	/	<	7 (<u> </u>	I	/	<	Ÿ	\	<	Beams & columns finishing (v or x)
Enchans			<	1	-	}		1	-	J))]	j)	Finishing of lofts (v or x)
- 1			<			7	1	<	7	1	X	X	1	X	X	Electrical junctions finishing (v or x)
finishing			\	I	-	}))	~		<	<	<	<	<	Window check ⁶ (v or x)
of Jan			X	1	İ	V	1	1	1		1	/	1	1	J	Tiles provision (v or x)
done			<	J)	<	1	<)	1	}	7		5	}	Sink provision & size
7			ſ	-	ſ	✓]	1		1	`\	Α.	\sim	\sim	<	Grooves for door frames (v or x)
or boy			}	1	<	1]	•	1	}	})	١.	1	Balcony & terrace sill top finishing(v or x)
TO THE PARTY OF TH			1	Ţ	1	<))	Ţ	1		/)	<	1	Screeding in bathroon & utility (v or x)
			1	1	l	<	1)	}	1	1	<	1	<	1	Screeding in 6" above FFL? (v or x)