Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Flat No. Company Company Project Project Project Manager Project Manager Project Manager SHIRCH Sign Checked By MD on Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed with further work after submitting ATR on QC report to QC team. Proceed with further work. ATR not required. SI. No. Additions Project Proje						
PMP Sign Date M. IGA Shidhar Sign Sign CHIRISH Sign Report filed and signed by PM? Sheet date I V 12/17 All pages signed by engineer & customer? Should define the point of the po	Flat No.	0-624	Other		Sl. No.	29925
M. Teya Sright Sign Ship Sign Chile(SH) Sign Chile(SH) Sign Chile(SH) Sign Chile(SH) Sign Date Date Date Date All pages signed by PM? In pages signed by engineer & customer? In pages signed by engineer & customer.	Company	PMR	Project	PMP	Phase	1
SHIRICH Sign 29899 Report filed and signed by PM? heat date (4 2 17 All pages signed by engineer & customer? I work on QC report to QC team. Proceed only after recheck by QC. roceed with work after submitting ATR on QC report to QC team. work only after making corrections pointed out in the QC report. ATR not required. work. ATR not required.	Prepared by	M. Tiga Sirdhur	Sign	94	Date	06/04/18
sheet date (4 2 17 All pages signed by PM?	Project Manager	SHIRISH	Sign	(A. inlia	Date	06/04/18
ons sheet date (y 2 / 17 All pages signed by engineer & customer? MD Sign For filling Submit ATR on QC report to QC team. Proceed only after recheck by QC. k. Proceed with work after submitting ATR on QC report to QC team. ther work only after making corrections pointed out in the QC report. ATR not required. ther work. ATR not required.	Previous stage report	no.	29899	Report filed and signe	d by PM?	Xes □No
C. Submit ATR on QC report to QC team. Proceed only after recheck by QC. k. Proceed with work after submitting ATR on QC report to QC team. ther work only after making corrections pointed out in the QC report. ATR not required. ther work. ATR not required.	Additions & alteration	ns sheet date	(4/12/17	All pages signed by er	ngineer & customer?	Yes No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	Checked By MD on	z'	MD Sign		For filling	☐Yes ☐No
Transition classical bands and the second se	Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Submit ATR on QC re Proceed with work afi ner work only after mak ner work. ATR not requ	port to QC team. Proceed ter submitting ATR on ing corrections pointedired.	eed only after recheck be QC report to QC team. I out in the QC report.	ay QC. ATR not required.	

nspection should be done att

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

After Plumbing & Electrical Check,

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing
- Mark **XXX** for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- ". Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes
- Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

	Yes No	ing attached	Approved revised drawing	Approv]Yes □No	from HO [Revised drawing required from HO
	╽┌		Signed by customer,	Signed]Yes ∏No		Signed by engineer,
	1					lteration sheet:	Remarks on additions & alteration sheet:
4	5		Meridia	in the	- 1		1
now Snewhoties	3	in not	harakt	ndit pina	boom	don't ion	B +
							15 Other
							14 Other
1	•	-	1	<	<	•	13 Kitchen
1	**	L	*		•	9	12 Thility / bulcony 3
هرت م	ļ		+	<	≺	<	11 Utility / linhowny 2
	-]	i i	<	〈	۲.	10 Dillity /balcony 1
				•	ţ	N	9 Lobby In
1	4			<	1	\	8 Dining
<	<	1		く	1	1	7 Drawing
Character	1						6 Teilet3
g	1	1	emerican)	[5 Bedroem-3-
de la composition della compos	1	\	(Κ.	→	1	4 Toilet 2 (ርፕ)
	1	1	١	<	1	1	3 Bedroom 2 (Kb)
1	-	1	1	<	<	1	
	4	ţ	1	<	1	1	1 Bedroom 1 (MB)
changeover (✓ or 🗙)		check (• or ×)	or		(v or X)	balcony & utility (• or ×)	S No Room
Placement of Generator	Placement of DR (or x)	Proper use of	Water	Electrical	CPVC &	Civil work	