Recommendation: Checked By MD on Previous stage report no. Apartment No Project Manager Prepared by Flat No. Company Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC Proceed with further work only after making corrections pointed out in the QC report. ATR not required Stop further work. Proceed with work after submitting ATR on QC report to QC team Soddung. N.S. BAC D. 703 Quality Control Check Repot. Aumay Sign MD Sign Other Others Sign Project とたが ь У Stage: After Brickwork (Apartments) Report filed and signed by PM? 202 スサス Date For filling Other Phase Date | Sl. No. Zes. 556 CB イニも仕 イニシナ Yes

Inspection should be done after:

Proceed with further work. ATR not required.

- brickwork is completed
- chicken mesh fixed
- after cleaning the apartment
- electrical conducting work is completed

Brickwork Check,

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark × for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark **XXX** for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4", 6" & 8" blocks must be checked.
- 5. All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC
- Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- 0. Diagonals of each room shall be equal. (Tolerance: 2")
- 1. Balcony sill level should be 3'3" from SFL. (Tolerance: 1")
- 2. Check room height with specified height. (Tolerance: 1")
- 3. Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- 14. Specify the No. of beams which are not aligned by more than I "in a room
- 5. Door frames must have black Japan coating and wood primer / pellambar a' cost of painter.

1 25	Ren	7	14	13	12	11	10	9	8	7	6	5	4	ယ	2	1	S No
THE NOW Y CC	•	Other	Other	Kitchen	Utility/balcony3	Utility / balcony 2	Utility / ba lcony 1	Lo bby 1	Dining	Drawing		Bedroom 3 CS	Toilet 2 ィイ	n 2	Toilet 1 みて	Bedroom 1 MS	Room
bed				<	1	\ \	V	1	<u></u>	<	١,	/	7	<u> </u>	\	7	Wall thickness
lay	-			7	١	7	Ý	}	74	<i>∱.</i>	}	35.	X	F	¥	X	Beds in walls (• or ×)
27				~	1	<u> </u>	<	\	5	ζ,	} .	\	<	\	<	1	Chicken mesh
70,	۲		2	<	Ţ	<	5	1	<	<	1	<	<u> </u>	5	5	<	External brickwork & beam joint (or x)
opera	_			<	1	<	<	1.	_	\	1	<	/	ς.	ζ,	\	Room Dimensions (v or x)
Done	-			1	1) }	3	}	1)	1	}	J)	})	Room Dimensions Difference in inches
				<	•	<	5	1	<	<	١	<	5	<	<	5	Diagonal (v or x)
				1	1	١	}	1		J	}	1))	}	1	Diagonal Difference in inches
				1	1	<	i	1	1)	}	1	١)	١	١	Balcony sill level
				<	1	<	<	1	5	5	1	\	ς	5	<	5	Room Height
				<	1	<'	<	1	<	5)	<	7	<	<	\	Plumb of walls (Good/Avg./Bad)
				<	1	<	<	, \	5	5	1	<	5	<	<	5	Alignment of beams and walls - Nos.

Door Frames & Windows check Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 1/2" after plastering.
- Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")

 Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33"from FFL and 35" or 36"from SFL. (Tolerance 1")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points.
- Thickness of platforms & lofts should be between 2 & 2.5".
- Provide single layer table brick at bottom of each door frame without threshold.

Rer	15	14	13	12	11	10	6	8	7	6	2	4	သ	2	1	S No
Remarks:	Other	Other	Kitchen	Utility/balcony 3	Utility / balcony 2	Utility / balcony 1	Lobby-1	Dining	Drawing	Toilet-3	Bedroom 3 んら	Toilet 2 C	n2 t	Toilet 1 いいて	Bedroom 1 Mら	Room
				}		<u> </u>	-	1	<	1	<	<	1	<		Door size, face and position (✓ or 🗙)
			1	j	١	\	1	5	<	1	<	5	\	<		Brick at bottom of door frame (v or X)
			1	1	1	<	١	١	<	1	<	\	5	\	5	Door lentil level (v or X)
			1	1	١	5	1,	1	<	{	<	5	5	5	<	Door diagonal check
			1)	1	5	ı	١	<	1	<	<	, <	, \	5	Door Plumb - two sides (✓ or 🗙)
			I	1	1	<	1	١	<	1		1	\	,	1	Door frame black Japan/ wood primer/Peelambar check (v or X)
			<	1	1	j	١	1	<	1	1	5	\	\	\	Windows lentil & sill level (✓ or 🗙)
			5	1	1	3	1	1	5	١	7	1	5	5	\	Windows size (✓ or 🗙)
			<	1	١	1	1	1	<	1	7	<	5	5	<	Windows - template depth & diagonal (v or X)
			<	1	1)	١	1	<	. 1	<	\	1	1	\	Windows - template powder coated (✓ or X)
			20	1	ſ)	1	(1	1	1)	,))	Loft & Kitchen platform required ? (Yes or No)
			ì	1	Į	-	١	1	1		{	١	١	1	1	Loft & Kitchen platform provided (v or × or NA)
			ì	1	1	1	1)		\		1		1	Loft & Kitchen platform slope (✓ or 🗙)