Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Flat No.	8-7-8	Other	1	Sl. No.	30163
Company	PMR	Project	MR	Phase	
Prepared by	M- 1 Ga Stidler	Sign	A	Date	03/05/18
Project Manager		Sign	こがあ	Date	05/05/18
Previous stage report no.	0.	30121	Report filed and signed by	d by PM?	YYes □No
Additions & alterations sheet date	sheet date	Unsold Flat	All pages signed by engineer & customer?		□Yes □No —
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Submit ATR on QC reports Stop further work. Proceed with work after s Proceed with further work only after making Proceed with further work. ATR not required Inspection should be done after.	Submit ATR on QC re Proceed with work aft r work only after mak r work. ATR not requ	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck learn. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Q Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR Proceed with further work. ATR not required.	y QC.	

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only)
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

After Plumbing & Electrical Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipcs.
- Height of DB box must be 6" below false coiling level or 12" below slab level.
- 11. In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Revi	Sign	Rem	2	Remarks	15	14	13	12	1	10		∞	7		-	-	1			╌	S No	
Revised drawing required from HO	Signed by engineer,	Remarks on additions & alteration sheet:		arks	Other	Other	Kitchen	Utility / balcony 3	Utility /-balcony-2	-Utility / balcony 1	Tabby I	Dining	Drawing	Toilet 3	Bedroom-s	Toilet 2 (Ci)	7 11	TOTIEL T (MI)	V	Redroom 1 (MB)	Room	
ed from HO		z alteration sheet:					(1	5	1	1	* 2 * *				((1	1	balcony & utility (vor	Civil work near pipes in
Yes No		Ungold Flat					<		<	<	1	1	<	,	()			1	<	1	(or x)	CPVC & PVC Check
Appro	Signed						<		<	<		K	\			4			<	<	(• or ×)	Electrical points check
Approved revised drawing anached	Signed by customer,						***			}		1		1		1	(ſ	١	1	check (or	Water proofing
WIII allaction	ttoched							**************************************	(!				1			\	1	1	j	check (or ×)	Proper use of fasteners
ă 1 7		T No							\$					<		3		1	-	ı		Placement of DB (• or ×)
								1	1		,	}	1	<		1	1	1	1	1	(v or x)	Placement of Generator