Vista Homes	Others Project	Stage: After Brickwork (Apa	SI. No. Phase
MAY	H	1. Vines Kumps Date	Date
Madhu	Sign ·	1 all War	Date ·
	33615	Report filed and signed by P	d by PM?
Apartment No	Other		Other
Checked By MD on	MD Sign		For filling
Recommendation:			
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.	t to QC team. Pro	ceed only after recheck b	y QC.
Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	corrections point	ed out in the QC report. A	ATR not required.
Proceed with further work. ATR not required.			•

after cleaning the apartment chicken mesh fixed Inspection should be done after:

brickwork is completed

Brickwork Check. electrical conducting work is completed

Notes:

- Mark ✓ for correct or minor, mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark **XX** for major mistake that requires correction by replacement or re-fixing.
- Mark **XXX** for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4", 6" & 8" blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork
- Joint between brickwork & beam on external side must be filled. Check room dimensions with working plan. (Tolerance: 1")
- 10. Diagonals of each room shall be equal. (Tolerance: 2")
- 11. Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- Check room height with specified height. (Tolerance: 1")
- Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- Specify the No. of beams which are not aligned by more than 1"in a room,
- 15. Door frames must have black Japan coating and wood primer / pellambar -- at cost of painter.

Ren	15	14	13	12	11	10	9	∞	7	6	5	4	w	2	_	S No
Remarks	Other	Other	Kitchen	Utility / balcony 3	Utility / balcony 2-	Utility-/ balcony 1	Eebby-1	Dining	Drawing	Toilet 3'	Bedroom-3	Toilet 2 C J	Bedroom 2 C. Bed	Toilet 1 M.7	Bedroom 1 M.Bed	Room
			(e \	£,	Ċ,	1	۲ .	۲,	box	-	۲.	ζ.	Γ,	۲.	Wall thickness (✓ or 🗙)
			ς.		ζ,	τ,		Κ.	Ψ,	ţ	9,00	۲,	٠,	۲.		Beds in walls (• or ×)
			E. A.	1		2,		<.	ζ.	S. east	2)-54	٠.		κ,		Beds in walls (• or ×) Chicken mesh (• or ×) External brickwork & beam joint (• or
			e,		1	1		١.	£" L	7					· s.	External brickwork & beam joint (v or x)
			ς,		< .	<	1	¢.	Κ.) . market	1,			e .	۲,	Room Dimensions
			ς,	1		ζ.,		Ę	<	B-) 1	موجي				ζ.	Room Dimensions Difference in inches
			*	* 1	₹.	× .		*.		Depart 1	1	Κ.		5.	₹,	Diagonal (• or ×)
			K							4		No.		٠.	e .	Diagonal Difference in inches
					,	<	i	3	-	2	27.4	-	1	,	,	Balcony sill level (• or ×)
			ď.	,	E.	6		<	-	and a	9	K.	-		ζ.	Room Height (v or x)
			(31666)	7	=	(315.04)			BUCH	3		1,	5		(100M	Plumb of walls (Good/Avg./Bad)
			6		ζ.,	, <,	. 1	<	. <	******	* 1	Κ.,	-	*	. <	Alignment of beams and walls - Nos.

Quality Control Check Repot.	Stage: After Brickwork (Apartments)
Quality of edges and corners in all rooms?	Good Avg. Bad
Specify rooms that need correction:	
Misc. Checks.	
Was 3.75 CFT proportion box provided?	Yes No
Condition of proportion box?	Good Nvg. Bad
Was the Apartment cleaned before starting brick work?	☐ Yes ☐ No [1] Cant' say
Is the Apartment cleaned for plastering?	Yes No
Wastage?	☐ High ☐ Medium ☐ Low
Storage of building material like bricks sand and cement.	☐ Good ☑ Avg. ☐ Bad
Drum (200 lts) provided for curing in each flat?	Yes No
Remarks:	

Door Frames & Windows check

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark **X** for minor mistake that requires minor correction.

 Mark **X** for major mistake that requires correction by replacement or re-fixing.
- Mark $\times \times \times$ for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 ½"after plastering. Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32" or 33" from FFL and 35" or 36" from SFL. (Tolerance 1")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- 10. Provide single layer table brick at bottom of each door frame without threshold.

Rer	15	14	13	12	11	10	9	8	7	6	5	4	w	2	1	S No
Remarks:	Other	Other	Kitchen	Utility / balcony-3-	Utility / balcony-2	Utility / balcony 1	Lobby-1	Dining	Drawing	Toilet 3	Bedroom-3	Toilet 2 (3.7)	Bedroom 2 C. 1860	Toilet 1 M. 1	Bedroom 1 M. Ba	Room
			garant.	9	ζ.	î,	ſ	Ì	Ĺ	j	Design and	ζ.	N,	47 V		Door size, face and position (✓ or X)
			است	1	۲.	7	ì		ζ.	7	eda)	۲,	۲,	۲.		Brick at bottom of door frame (✓ or 🗙)
			4	1	ς.				ζ.	O Mayorani	American Co.	₹.	ζ.	. ·	۲.	Door lentil level (v or X)
			I.	- Crange d	7				Κ,	1	1	<	۲.	۲,	ζ,	Door diagonal check (v or X)
			Buck	1	K,	1	ì		۲,	alice of	1	₹*,	ς.	5.	۲	Door Plumb - two sides (✓ or 🗙)
			معدور	2	۲,			1	ζ.	Č.		Ć,	7		τ,	Door frame black Japan/ wood primer Peelambar check (• or ×)
			۲,		<	1		i	<.		f,	۲,	ς.	ξ.	ζ.	Windows lentil % sill lovel
			۲.		5		(1	ζ.	1	100 m	۲,	۲.	€.,	Ľ.	Windows size (✓ or 🗙)
			ĸ,		ζ,		4	Apr A	<	,	9	5	5.	ς,	<	Windows - template depth & diagonal (✓ or 🗙)
			ζ,	i.	¢,	1	â	Min and	Κ,	3	g et	₹,	۲.	<	Υ,	Windows - template powder coated (✓ or 🗙)
			Y 65	d ,				61.00	\$,	1	į	Loft & Kitchen platform required ? (Yes or No)
			<,			9			p		i		ļ.	1	N	Loft & Kitchen platform provided (✓ or × or NA)
			ζ.	,		1		1			i		İ	1	1	Loft & Kitchen platform slope (✓ or 🗙)