Quality Con	Quality Control Check Repot.	Stage: Before Casting Slab (Apa	lab (Apartments)	
Block No E-3,4,5,6 flots Slab No.	ots Slab No.	03	S1. No.	* 74231
Company BNC	Project	MFG	Phase	口
Prepared by P Sou Kumar	Sign	Pres	Date	18/5/17
Project Manager S.V.S. wha Reddy	Sign	mild	Date	4115/81
Previous stage report no.	26944	Report filed and signed by PM?	ed by PM?	Yes □No
Checked By MD on	MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not Proceed with further work. ATR not required.	Oreport to QC team. It after submitting ATI making corrections porequired.	Proceed only after recheck on QC report to QC team inted out in the QC report.	by QC. a. ATR not required.	

Slab Check.

Notes:

- Inspection should be done before casting of slab at each stage (e. when the slab is ready for easting. Prepare Slab Dimensions Check Plan as follows.)

- Show order dimensions of slab. (Tolerance 2") Show length and width of balconies (Tolerance 1") Show inner dimensions of duets. (Tolerance 1") Show location of sunken slab.
- Print an A3 size plan.
- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted.

4. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it	en colour. Circle each incorrect d	limension with red colour a	and mention actual dimension next to	it.
Slab Dimensions Check Plan enclosed?	sed?	☐ Yes ☐ No		
Staircase - mid landing!	Specified ht: 3.6"	Actual ht: 3、よい	Within tolerance of 1/2"?	Yes No
Staircase - mid landing 2	Specified ht: 31.6"	Actual ht: 31,6"	Actual ht: 31.6" Within tolerance of 1/2"?	[√Yes []No
Staircase width	Specified wd: 10.3" Actual wd: 10.3" Within	Actual wd: 101. 3	tolerance of 1/2"?	Yes No
Staircase slab thickness	Specified: 5"	Actual: 51	Within tolerance of 1/4"? Yes No	√Yes □ No

Quality Control Check Repot. Stage: Before Casting Slab (Apartments)

Quality of centering, rod bending and concreting? Quality of centering, rod bending and concreting?	Good Avg. Bad
18"extension to beam bottom runners on outer side provided? Ouality of Bracing Provided?	Yes No
Quality of Bracing Provided? Alignment of beams on outer side?	☐ Good ☐ Avg. ☐ Bad ☐ Avg. ☐ Bad
Shuttering leveling?	√] Good Avg. Bad
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Correct Needs correction
Remarks:	

Slab Steel check.

Notes:

- Mark v for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XX for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Slab (Apartments)

			Remarks:
Good[<	Steel check – slab extensions, joints	16.
Good	1000	Steel check – floating columns	15.
Good Avg.	<	Electrical Conducting	14.
Good Avg.	<	Steel Check - Column steel overlapping length and cranking	13,
Good Avg. Bad		Covering blocks for slab	12.
\sqrt{Good \sqrt{Nvg. \sqrt{Bad}}}	< *	Steel Check - Slab Extra Bars	
Good Avg.		Steel Check Slab cranking & chairs	10.
Good		Steel Check - Slab spacing of bars	9.
Good Avg.		Steel Check - Slab size of bars	&
Good ☐ Avg. ☐ Bad	<	Depth and width of beams	7.
☐ Good ☐ Avg. ☐ Bad		Covering blocks for beams	6.
<	<	Steel Check - Beams Bearing	5.
NGood		Steel Check - Beams Overlapping & Cranking	4.
☑ Good ☐ Avg. ☐	<	Steel Check - Beams Extra Bars	3.
☑Good ☐ Avg. ☐ Bad		Steel Check - Beam size of bars	2.
Good Avg.		Steel Check - Beam no of rods	
<u> </u>	Quantitative Check (vor x)	Item	S No
-			~