Quality
Control
Check
ty Control Check Repot. Stag
Stage
 :: After
-
3rickwo
3rickwork (Ap
Stage: After Brickwork (Apartments

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	Checked By MD on MD Sign For filling	Apartment No Other Other	Previous stage report no. Q877 Report filed and signed by PM?	Project Manager Sobba Reddy Sign Klindermy Date C	Prepared by Mileja Snidhw Sign A Date 0	Company BNC Project MFG Phase	Flat No. E-406 Others SI. No.
ck by QC. am.	For filling Yes No	Other			Date 09 01 18		SI. No. 28939

- brickwork is completed
- chicken mesh fixed
- after cleaning the apartment
- electrical conducting work is completed

Brickwork Check,

Notes:

- Mark ✓ for correct or minor mistake which does not require correction Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4", 6" & 8" blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in cach and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- 10. Diagonals of each room shall be equal. (Tolerance: 2")
- 11. Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- Check room height with specified height. (Tolerance: 1")
- Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- 14. Specify the No. of beams which are not aligned by more than I"in a room.
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.

Ren	15	14	13	12	11	10	9	∞	7	0	Ŋ	4	w	2		S No
Remarks	Other	Other	Kitchen	Utility/balcony3	Utility / balcony-2-	Utility/ balcony 1	-Lobby 1	Dining	Drawing	Toilet 3	Bedroom 3 (Ub)		n 2	Toilet 1 (MT)	n 1	Room
			<	1	<	5		4	<	İ	く	<	<	<	<	Wall thickness
			<	-	<	<		۷,	ζ.	t	~	く	<	<	<	Beds in walls (or x) Chicken mesh (or x) External brickwork & beam joint (or
			<	1	<	ζ	1	<	く		イ	<	<	<	<	Chicken mesh
			<	1	<	5		4	<	(/	~	\	~	<	External brickwork & beam joint (or x)
			<	1	<	5	1	<	۷,	Ţ	1	<	7	<	<	Room Dimensions
			1		\	J	1	\	\	(-)	1	١	J	Room Dimensions Difference in inches
			<	[<	ζ		۷,	<	{	~	<	<	<	<	Room Dimensions Difference in inches Diagonal (v or x)
			1	1	1	1					1	١	1	1	ĵ	Diagonal Difference in inches Balcony sill level (or x)
					1	}	•	\	1	1	,	1		[(Balcony sill level (v or x)
					<	5		4	4	-		ζ	4	5	<	Room Height (• or ×)
		<u> </u>	to		-	ta		٦,	Na	I	۶	ر ع	= }	2	tore	Plumb of walls (Good/Avg./Bad)
		,	?	1	<	<		<	5	1		\	<u> </u>	5	3	Alignment of beams and walls - Nos.

Ouality Control Check Repot.	Stage: After Brickwork (Apartments)
Quality of edges and corners in all rooms?	☐ Good ☑ Avg. ☐ Bad
Specify rooms that need correction:	
Was 3.75 CFT proportion box provided?	\(\frac{\gamma}{\text{res}}\) \(\sigma\) No
Condition of proportion box?	Good Avg. Bad
Was the Apartment cleaned before starting brick work?	Yes No X Cant' say
Is the Apartment cleaned for plastering?	⊠Ýes □No
Wastage?	☐ High ☐ Medium ☐ Low
Storage of building material like bricks sand and cement.	☐ Good ☐ Avg. ☐ Bad
Drum (200 lts) provided for curing in each flat?	□Ycs □No
Remarks:	

Door Frames & Windows check

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 ½"after plastering. Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33"from FFL and 35" or 36"from SFL.
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. (Tolerance 1")
- Provide single layer table brick at bottom of each door frame without threshold.
 - Thickness of platforms & lofts should be between 2 & 2.5".

Rer	15	14	13	12	11	10	9 .	œ	7	<u>ب</u>	<u>بر:</u>	_	သ	2	<u> </u>	S No
Remarks:	Other	Other	Kitchen	Utility/balcony-3	Utility / baleony-2-	Utility / balcony 1	Lebby 1	Dining	Drawing	Thilet 3	Bedroom 3 (46)	Toilet 2 ((\(\tau\))	Bedroom 2 (KB)	Toilet 1 (MT)	Bedroom 1(いら)	Room
			1	1	<	-	•		≺.		く	<	<	<	<	Door size, face and position (✓ or X)
			1	-	<]	1				۷,	1	~	١		Brick at bottom of door frame (✓ or 🗙)
			l	1	<		1	**	<	[7	<	<	<	<	Door lentil level (✓ or X)
				1	<	}	1	1	<	1	く	<	<	<	<	Door diagonal check (✓ or X)
			١	-	<	{	ţ	į	5	1	<	<	<	<	<	Door Plumb - two sides
			1	1	<	1		1	Ś	1	<u>ر</u>	<	<	ζ		Door frame black Japan/ wood primer/Peelambar check (vor X)
	2		<		1	}	1	ļ	1	1	<	ζ	<	<		Windows lentil & sill level (✓ or 🗙)
			<	1	1	1	1	1	J	1	<	<	<	<	<	Windows size (✓ or 🗙)
			<	1	1	97	1	1	1		V.	<	<	<		Windows - template depth & diagonal (✓ or 🗙)
			<		ĺ	1	1	1	-	l	<	<	۲	<		Windows - template powder coated (✓ or 🗙)
			20	<u> </u>	1	1	1	1	J	1	(1	ļ	1)	Loft & Kitchen platform required ? (Yes or No)
			1	1	1	١		1	1	ı	(1	{	1	}	Loft & Kitchen platform provided (✓ or X or NA)
		Control Service	9	1)	1	1		ł	Į	Į	Į	-	1	Loft & Kitchen platform slope (✓ or 🗙)

Quality Control Check Repot. Stage: After Brickwork (Apartments)