Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Project Manager Subsect of the project Manager Sign Date Lylulg	Flat No.	90K-3	Other		Sl. No.	30016
Subject to Canal Sign Subject to Case 25.915 Report filed and signed by PM? Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required.	Company	BNC	Project		Phase	
Submit ATR on QC report to QC team. Proceed only after recheck by QC. work. Proceed with work after submitting ATR on QC report to QC team. urther work ATR not required.	Prepared by		Sign	LP. V.J.		8114/4/
ations sheet date Cosso 25098 Report filed and signed by PM?		Subba Reld	Sign	1221		SILMINI
ations sheet date Continue C	Previous stage report n	Ю.		Report filed and signe		√Yes □No
ork. Submit ATR on QC report to QC team. Proceed only after recheck by QC. ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR not required.	Additions & alterations	s sheet date	Mosold	All pages signed by en	gineer & customer?	☐ Yes ☐ No
ork. Submit ATR on QC report to QC team. Proceed only after recheck by Qu ork. Proceed with work after submitting ATR on QC report to QC team. urther work only after making corrections pointed out in the QC report. ATR urther work. ATR not required.	Checked By MD on		MD Sign		For filling	□Yes □No
Inspection should be done after:	Recommendation: Stop further work. Stop further work. Proceed with furthe Proceed with furthe Inspection should be done at	Submit ATR on QC re Proceed with work after r work only after mak r work. ATR not require:	port to QC team. Proce ter submitting ATR on ing corrections pointed ired.	eed only after recheck be QC report to QC team. out in the QC report. A	y QC. \TR not required.	

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request

After Plumbing & Electrical Check.

- Mark \vee for correct or minor mistake which does not require correction Mark \times for minor mistake that requires minor correction.

 Mark \times for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes. Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

tached
Signed by customer,
point not movided
}
-
<
<
1
)
)
}
}
]
}
5
}
proofing fasteners check (v or x)
Proper use of