Quality Control Check Repot		Stage: After Brickwork (Apartment	k (Apartments)	
C-701	Others	1	SI. No.	2
かべつ	Project	N.FC	Phase	<u> </u>
Mr. Teja Sondhur Sign	Sign	44	Date	23

Flat No.	G-701	Others	1	Sl. No.	29625
Company	のべつ	Project	なたの	Phase	
Prepared by	Milia Souther Sign	Sign	4	Date	13/03/18
Project Manager	Million Reddy	Sign		Date	13/03/18
Previous stage report no.	no.	29171	Report filed and signed by PM?	d by PM?	NYes □No
Apartment No		Other		Other	
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Stop further work. Proceed with furth	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not	eport to QC team. Proces the submitting ATR on ting corrections pointed ired	eed only after recheck QC report to QC team I out in the QC report.	by QC. ATR not required.	
Proceed with furth	Proceed with further work. ATR not required	ired.			

Inspection should be done after:

- brickwork is completed
- chicken mesh fixed
- after cleaning the apartment
- electrical conducting work is completed

Brickwork Check,

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4", 6" & 8" blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- 10. Diagonals of each room shall be equal. (Tolerance: 2")
- 11. Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- 12. Check room height with specified height. (Tolerance: 1") Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- Specify the No. of beams which are not aligned by more than 1"in a room.
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.

Ren		15	14	13	12	11	10	9	∞	7	6	S	4	ယ	12	_	S No
Remarks i) Thue	Onto	Other	Other	Kitchen	-Utility-/-balcony 3	Utility / baleony 2	Utility/balcony 1	Lobby 1	Dining	Drawing	Teilet-3	Bedroom3	Toilet 2 (CT)	Bedroom 2 (Kb)	Toilet 1 (MT)	Bedroom 1 (M&)	Room
were				<	•	<	<	-	<	<	1	-	V	1	<	<	Wall thickness (v or x)
6				<	1	<	<	-	< ,	<	1	1	J.	<	<	<	Beds in walls (• or ×)
dom				<		<	<		<	<	-	-	~	<	<	<	Chicken mesh (✓ or ×)
interna				<		<u> </u>	<		~	<		-		<	<	<	External brickwork & beam joint (• on
med				<		~	>		~	<		1	/	<	<	<	Room Dimensions
Customer				-		1			/	1	-	1	1	١		1	Room Dimensions Difference in inche
mer				<	1	<	<	ſ	<	<		1	۷,	<	<	<	Diagonal (• or ×)
Chan				1	1		1				1	1	1	1	1	1	Diagonal Difference in inche
gu,				1	1	1	J		\)	-]	\	}	}	}	Balcony sill level
				<	7	<	5	ſ	<	<	-	1	<	<u>ح</u>	<	<	Room Height
				Arg]	14	Ava	1	ار	Arg	1	1	٦ (3	Ava	Plumb of walls (Good/Avg./Bad)
				\	1	7	5		1	5	1	1	<	5	<	5	Alignment of beam and walls - Nos.

Quality Control Check Repot. Stage: After Brickwork (Apartments)

Quality Control Check Repot.	Quality Control Check Repot. Stage: After Brickwork (Apartments)
Quality of edges and corners in all rooms?	☐Good MAvg. ☐Bad
Specify rooms that need correction:	

Misc, Checks.	
Was 3.75 CFT proportion box provided?	☐Yes ☐No
Condition of proportion box?	☐ Good ☐ Avg. ☐ Bad
Was the Apartment cleaned before starting brick work?	Yes No Cant' say
Is the Apartment cleaned for plastering?	No No
Wastage?	☐ High ☐ Medium ☐ Low
Storage of building material like bricks sand and cement.	Good Avg. Bad
Drum (200 lts) provided for curing in each flat?	No □No
Remarks:	
2.00	

Door Frames & Windows check

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 ½" after plastering. Lentil level should be 7'3" from SFL & 7' from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33"from FFL and 35" or 36"from SFL. (Tolerance 1")
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points.
- Thickness of platforms & lofts should be between 2 & 2.5".
- Provide single layer table brick at bottom of each door frame without threshold.

Ren	15	14	13	12	1	10	9	8	7	6	S	4	3	2	1	S No
Remarks:	Other	Other	Kitchen	Utility/balcony3-	Utility / balcony 2-	Htility/balcony 1	Labby-1	Dining	Drawing	Toilet-3	Bedroom 3	Toilet 2 (Cr)	Bedroom 2(KB)		Bedroom 1 (M&)	Room
				1	Ż		ļ	\	<		1	<	<	<		Door size, face and position (✓ or ×)
			1	1	1	{	1	1	1	1	1	1	<	1		Brick at bottom of door frame (✓ or 🗙)
				-	<	İ	[1	<	-	1	۲,	5	<	5	Door lentil level * (v or X)
			{	1	<	1		1	<	1	1	<	<	1	<	Door diagonal check
			1	1	<	1	1	1	<	1		<	<	<	×	Door Plumb - two sides
			1	1	<	1		1	<	1		<	<	<	<	Door frame black Japan/ wood primer/Peelambar check (v or X)
			<		1	1	1	1		1	1	<	<	<	<	Windows lentil & sill level (✓ or 🗙)
			<	1	1	1		1			1	2	. <	(1	Windows size (✓ or 🗙)
			<	1	1	1	ſ	1	1	1	1	<	5		, {	Windows - template depth & diagonal (✓ or 🗙)
			<		1	1					1	<	<	<	, <	Windows - template powder coated (✓ or 🗙)
		8	70	, 1	(1	1	1	1	١	Loft & Kitchen platform required? (Yes or No)
			1	1		1			1]	١	1	1	1	Loft & Kitchen platform provided (✓ or X or NA)
			1	1			1		1 1		1)	1	١	1	ſ	Loft & Kitchen platform slope (✓ or 🗙)