	Suality Control Check Report	Chality Contuct Charles
NIDAVITED TATES OF W	Itage After Reinlagori,	
A par unents	(Amout-	

1			Service of the servic	Children trackers	
Flat No.	F-103	Others	•	Sl. No.	91/02
Company	BNC	Project	MEZ	Phase	1 675
Prepared by	A COLUM	Sion			1
Designat Monage	" Lys Sidher	ugic	124	Date	414018
Project Manager	SVSUBBE Roddy	Sign	N	Date	0104114
Previous stage report no.	no.	0/0/0	Part !		グルのナニア
Variable 1 of 1		文に対する	Report filed and signed by PM?	d by PM?	Yes No
Aparument NO		Other		Other	
Checked By MD on		MD c:			
TO CITE OF THE CITE		IMID Sign	-	For filling	Yes No
Recommendation:					
Stop further work.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.	port to QC team. Proce	ed only after recheck b	y QC.	
Proceed with furth	Proceed with further work only after making corrections pointed out in the OC report ATP not required	ing corrections pointed	QC report to QC team.	TP not required	
Floceed With Jurth	rioceed with further work. ATR not required	red.		. <u>T</u>	
inspection should be done after:	after:				

- brickwork is completed
- chicken mesh fixed
- after cleaning the apartment
- electrical conducting work is completed

Brickwork Check.

Mark \vee for correct or minor mistake which does not require correction

Ą

- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4", 6" & 8" blocks must be checked.
- All walls should have 2 beds of about 2"to 3"thickmess with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork.
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- 10. Diagonals of each room shall be equal. (Tolerance: 2")
- 11. Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- Check room height with specified height. (Tolerance: 1")
 Check plumb of walls where ever it appears to be out of no Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- Specify the No. of beams which are not aligned by more than 1"in a room.
- Door frames must have black Japan coating and wood primer / pellambar at cost of painter.

	Remarks	15	+-	13	12	11	10	9	∞	7	0	1	۸.	4	ယ	2	-	S No
	arks	Other	Other	Kitchen	Utility/balcony-3	Utilify / balcony 2	Utility-/ balcony 1	Labby-1	Dining	Drawing	Hotlet 3	(ab) cmoomer	2/	Toilet 2 (Cr)	n 2	Toilet 1 (MT)	Bedroom 1 (Mg)	
				<		<	<u>ح</u>	{	4	<	1	<	1	, ,	<	<	۲	Wall thickness
				<	1	<	<	1		۲	1	<	<	, /	, ,		<	Beds in walls (v or x)
			-	<	1	< <		i	1	\	1	<	<	,	< <		\	Chicken mesh
		_	-	1	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	\\ - -	\		<\\-	S	(_	〈	<	<	,	5	External brickwork & beam joint (• or ×)
			\ 	1	\ - -	\\ -	, 1		< <		1	_	<	<	, <	\	<	Room Dimensions (• or ×)
		-	1	1	1	1 1	1		1 1	1			[1	\	1		Room Dimensions Difference in inches Diagonal (v or x) Diagonal Difference in inches Balcony sill level v or x)
	_		<	1	<	K	(1	<	, (2		<	4	<	<		Diagonal
				1	1	1	1	1	<u> </u>	1		(1	ſ	1]	Diagonal - Difference in inches
			1	1	,	1	1	1	1	t	1		1	۱ 	ı	1		Balcony sill level
	-		<	1	<	<		<	3	1	K		1	\	<	<	F (Room Height
		,	Res	1		Ava	1	11	3	1	=	=	2		=	Ala	P (0	lumb of walls Good/Avg./Bad)
			(1	<	<	1	<	く	1	<	K	<	,	<	<	A	lignment of beams and walls - Nos.

rol Check Repot.	Stage: After Brickwork (Apartments)
ooms?	Good Avg. Bad
Specify rooms that need correction:	
Misc. Checks.	
Condition of 1 proportion box provided?	Yes No
Condition of bioboution pox;	☐ Good ☑ Avg. ☐ Bad
To the A partition cleaned before starting brick work?	Yes No Cant' say
as the Apartment cleaned for plastering?	
Wastage?	- 1 1
storage or building material like bricks sand and cement.	Good Ave. Bad
Drum (200 lts) provided for curing in each flat?	Vives I No
Remarks:	
3	
Door Frames & Windows check Notes:	,

XID.

- Mark ✓ for correct or minor mistake which does not require correction

- Mark X for minor mistake that requires minor correction.

 Mark X for major mistake that requires correction by replacement or re-fixing.
- Mark $\times \times \times$ for major mistake that cannot be corrected.
- Window template depth should be between 2 to 2 ½"after plastering. Lentil level should be 7'3"from SFL & 7'from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32" or 33" from FFL and 35" or 36" from SFL.
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- 10. Provide single layer table brick at bottom of each door frame without threshold,

Ren	15	14	13	12	11	10	ပ	∞	7	0	, 5	4	ر د	2/2	ــا د	S No
Remarks:	Other	Other	Kitchen	Utility_balcony_3	Utility /-baleony 2	Utility / balcony 1	Lobby 1	Dining	Drawing	Lattet 3	Bedroom 3 (46)		0 2 0	٦/	, n n	
			1	1	<	-	1	I	4	1	<	<	<	1	. <	Door size, face and position (v or x)
			7	1	1	1	Ţ	1	1		4	1	<	, ,	<	Brick at bottom of door frame (v or x)
]	****	1	-	Ţ	1	〈	1	~	4	<	, 3	5	Door lentil level
			1	١	<	١	1	1	3	ļ	7	<	<	<	<	Door diagonal check
			1	1	<	1	1	1	<	{	~	4	<	1	<	Door Plumb - two sides
		_	1	1	<	{	1	١	5	I	<	<	<	<)	Door frame black Japan/ wood primer/Peelambar check (or X)
	3		<	1	1]	\ ,	1	1	1	4	۷	4	4		Windows lentil & sill level (✓ or 🗙)
		,	<	1	1	1	1	ſ	1	1	1	<	<	<	<	Windows size (✓ or 🗙)
		-	<	1	1	1	1	\	S	(4	4	<	۷	<	Windows - template depth & diagonal (✓ or 🗙)
			<	1	i	1	1	,	•	1			<	<	<	Windows - template
		-	3	1	1		1	1	1	1	((1	1	Loft & Kitchen platform required ? (Yes or No)
		,		1	1		1	1	}	(1 1			1	(Loft & Kitchen platform provided (v or x or NA)
		1			1	1	f	1		***		1	1	j	\ I	Loft & Kitchen platform