Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Flat No.	F-301	Other	-	SI. No.	28876
Company	BNC	Project	MFG	Phase	[=]
Prepared by	M. Tela Svidhur	Sign	T D	Date	05/01/18
Project Manager	Subba Reddy	Sign	1 & 1	Date	05/01/18
Previous stage report no.		28816	Report filed and signed by PM?	d by PM?	☐ Yes ☐No
Additions & alterations sheet date	sheet date	Unsold Flat	All pages signed by engir	neer & customer?	☐Yes ☐No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by (Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATI Proceed with further work. ATR not required. Inspection should be done after.	commendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after s Proceed with further work only after making a Proceed with further work. ATR not required pection should be done after.	port to QC team. Proce er submitting ATR on ing corrections pointed ired.	scommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	y QC.	

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request

After Plumbing & Electrical Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark X for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- Height of DB box must be 6" below false ceiling level or 12" below slab level.
- In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.

Quality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)

Rev	Sig	Rer		Rer	15	14	13	12	=	10	9	∞	7	6	5	4	w	2	-	S No
Revised drawing required from HO	Signed by engineer,	Remarks on additions & alteration sheet:		Remarks Note:	Other	Other	Kitchen	-Utility / balcony 3.	Utility / balcony 2	Utility / balcony 1	Labby 1	Dining	Drawing	Foilet 3	Bedroom 3 (იტ)	Toilet 2 (CT)	Bedroom 2(以3)	Toilet 1 (MT)	Bedroom I (MB)	Room
from HO		lteration sheet:		Wall mi			1		į	<	r	1		1	(1	Civil work near pipes in balcony & utility (• or x)
]Yes ∏No]Yes □No	Unsold Flat		mixtuus net	0		<		<_	<	1	-	1	1	(ς	•	く		CPVC & PVC Check (~ or ×)
Approv	Signed	Flat		Provided		10	<_	1	4	<	1	<	<	(<	<	<	<	ς	Electrical points check
Approved revised drawing attached	Signed by customer,			S.					-	1	1	١			1	1	ſ	1	1	Water proofing check (• or ×)
ing attached				both M. Toild			I		•	}		1	1		ſ	1	1	١	(Proper use of fasteners check (• or ×)
Yes No]Yes No			n				-	1	1		-	1		1	ļ	ſ	1	1	Placement of DB (• or ×)
)			C. Toild.				1	1	1			ļ		(ſ	ſ	-	J	Placement of Generator changeover (• or ×)