Juality (
Juality Control Check Repot. Stage: After Plumbing & Electrical (Apartments)
heck Re
pot.
Stage: 1
fter Plu
mbing &
Electric
al (Apai
rtments

		Sl. No.	7/160
Flat No.	Officer	Dhaca	
Company 11 9 10 HAVING	Project Vista Homes	owe2 rhase	
hu Common	Sign	Date	110 9
D'SUM A CAO		Dota	
Project Manager 7. Who have	Sign	Date	11/0/12
Designation report no		Report filed and signed by PM?	Yes No
Trevious subservers.	0101	I le main a projetomer?	NO No
Additions & alterations sheet date	All pages sign	All pages signed by engineer & customer.	
		For filling	Yes No
Checked By MD on	MD Sign	Summy 10.1	
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.	eport to QC team. Proceed only after r	echeck by QC.)C team.	
Stop further work. Proceed with work after submitting AIK on QC report to QC report. ATR not required. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	fter submitting AIK on QC report to Qking corrections pointed out in the QC	report. ATR not required.	
Proceed with further work. ATR not required	uired.		

Inspection should be done after:

- after cleaning the apartment.
- before starting painting, tiling & flooring.
- electrical conduct, waterproofing & plumbing work is completed (for stage II only).
- additions & alterations is finalized and signed. In case there are no additions and alterations printout of email by PM to CR confirming the same must be
- additions & alterations sheets to be transferred to QC file. QC to check if A&A are made as per request.

After Plumbing & Electrical Check.

Mark ✓ for correct or minor mistake which does not require correction

- Mark \times for minor mistake that requires minor correction. Mark \times for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected. Location of CPVC & PVC fittings must be checked as per measurements given in circular. Tolerance 1".
- Location, height and spirit level of electrical points must be checked as per measurements given in circular & plan. Tolerance 1".
- Civil work near pipes in balcony & utility must be neat and mortar should be removed from the pipes.
- Water proofing must cover all pipes & check height above SFL.
- Fasteners must be used as specified in circular. Especially check fixing of PVC pipes.
- Height of DB box must be 6" below false ceiling level or 12" below slab level.
- 11. In case of many changes in civil work, electrical work and plumbing work, a new drawing must be prepared at HO and approved by MD.