Recommendation; Checked By MD on Apartment No Previous stage report no. Project Manager Prepared by Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Milaa Subba BXC 2600 Quality Control Check Repot. Kaddy いてはか Sign Other MD Sign Project Others 28152 Stage: After Brickwork (Apartments) Report filed and signed by PM? S1. No. For filling Other Date Date Phase イYes 50 Yes 0388

No

No

Flat No Company

(4)
Ü
ŏ
C11C
□
_
Ħ
pluous
0
=
=
P
ĕ
5
9
\Box
œ
20
i-
퐀
77

Proceed with further work. ATR not required.

Stop further work. Proceed with work after submitting ATR on QC report to QC team.

Proceed with further work only after making corrections pointed out in the QC report. ATR not required

- brickwork is completed
- chicken mcsh fixed
- after cleaning the apartment
- electrical conducting work is completed

Notes: Brickwork Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- Wall thickness should be as per plan. Use of 4", 6" & 8" blocks must be checked
- All walls should have 2 beds of about 2"to 3"thickness with one no. 6 mm or 8 mm rod with M15 CC.
- Chicken mesh should be used in each and every joint between RCC & Brickwork
- Joint between brickwork & beam on external side must be filled.
- Check room dimensions with working plan. (Tolerance: 1")
- 10. Diagonals of each room shall be equal. (Tolerance: 2")
- 11. Balcony sill level should be 3'3"from SFL. (Tolerance: 1")
- Check plumb of walls where ever it appears to be out of plumb. (Tolerance: 1/2")
- Check room height with specified height. (Tolerance: 1")
- Specify the No. of beams which are not aligned by more than 1"in a room. Door frames must have black Japan coating and wood primer / pcllambar - at cost of painter.

- Re	15	14	13	12	11	_10	9	∞	7	6	U	4.	. u	3 N	۔ د	-
Remarks		-	 	1			Ŧ	_		ļ.,		┸	-	\perp	-	S No
ks	Other	Other	Kitchen	Utility/balcony-3	Utility / halcony 2	Utility/balcony	Lobby 1	Dining	Drawing	Loulet-3	Bedroom 3 (48)	Toilet 2 ((T)	Bedroom 2 (大多)	-إ-	\\	
	_			<u></u>	2	_										
			<	1	4	<	(۷,	<	1	<	<	<	<	. <	Wall thickness (v or x)
			<	1	<	<	1	~	<		<	K	<	<	, <	Beds in walls (or x)
			<	1	4	`\		<	<	\	<	<	<	<	<	Beds in walls (v or x) Chicken mesh (v or x) External brickwork & beam joint (v or
		4	\	1	<		1	۷.	<	1	<	<	<	<	<	External brickwork & beam joint (or x)
				1	< <			<	<	\	~	<	<	<	5	Room Dimensions
			1	1	\ 1		l .)	1	(1	١	1		Room Dimensions Difference in inches Diagonal (v or x)
				!	</td <td>, </td> <td>\</td> <td></td> <td></td> <td>1</td> <td><</td> <td><</td> <td><</td> <td><</td> <td><</td> <td>Diagonal (v or x)</td>	,	\			1	<	<	<	<	<	Diagonal (v or x)
					1 1		!	\		1	(1	١)	1	Macanal II.
			1		1	1		١		1	1	1	,	1	1	Difference in inches Balcony sill level (v or x)
		<			< <	1	<	<	7	1		<	\	<	<	Room Height (v or x)
	(2,2	*	7	2,50	4		5,11	2)		=	-	7	4	Plumb of walls (Good/Avg./Bad)
		<			<	1	<	<) <	~	,	<	<	<	Alignment of beams and walls - Nos.

Quality Control Check Repot.	Stage: After Brickwork (Apartments)
Quality of edges and corners in all rooms?	Good Avg. Bad
Specify rooms that need correction:	
Misc. Checks.	
Was 3.75 CFT proportion box provided?	⊠Yes ∏No
Condition of proportion box?	☐ Good ☑ Avg. ☐ Bad
was the Apartment cleaned before starting brick work?	☐ Yes ☐ No ☐ Cant' say
Is the Apartment cleaned for plastering?	VYes No
Wastage?	☐ High ☐ Medium ☐ Low
Storage of building material like bricks sand and cement.	Good-Avg. Bad
Drum (200 lts) provided for curing in each flat?	Yes No
Remarks:	
Door Frames & Windows check Notes:	

- Mark ✓ for correct or minor mistake which does not require correction
- Mark \times for minor mistake that requires minor correction.
- Mark XXX for major mistake that cannot be corrected. Mark XX for major mistake that requires correction by replacement or re-fixing.
- Window template depth should be between 2 to 2 1/2" after plastering. Lentil level should be 7'3" from SFL & 7' from FFL. (Tolerance 1")
- Lofts should be at a height of 7'to 7'3" from FFL. Kitchen plat from should be at a height of 32"or 33"from FFL and 35" or 36"from SFL.
- Slopes of lofts and kitchen platforms to be checked by using 12"spirit level and check height from floor from 2 or 3 points. Thickness of platforms & lofts should be between 2 & 2.5".
- 10. Provide single layer table brick at bottom of each door frame without threshold.

Rei	J [14	13	12	11	10	9	∞	7	6	5	4	ω	2	—	S No
Remarks:	Other	Other	Kitchen	-Utility/balcony-3-	Utility / baleony-2	Utility/balcony l	Lebby 1	Dining	Drawing	Toilet 3	Bedroom 3 (GB)	Toilet 2 ((¬¬)	n 2	Toilet 1 (MT)	Bedroom I (MB)	Room
			1	[(1		1	<	1	۷.	ζ,	K	<		Door size, face and position (v or X)
			1	{	ſ	(1	1	ſ	ļ	\	Ì	<	*	<	position (v or x) Brick at bottom of door frame (v or x) Door lentil level (v or x) Door diagonal check (v or x)
			1	(<	1	1	1	<	ļ	7	<	<	۲,	ζ	Door lentil level (✓ or 🗙)
			1	-	<u> </u>)	1	Ţ	<		~	<	<	<	ς	Door diagonal check (v or x)
			•		く	•	{	1	4		4	<	<	<	5	Door Plumb - two sides (✓ or X)
			1		〈	1	[1	<	-	4	<	4	く	<	Door frame black Japan/ wood primer/Peelambar check (v or X) Windows lentil & sill level (v or X) Windows size (v or X)
			<	1	1	1	1	(1	[_	<	4	<	<	Windows lentil & sill level
			<	{	1	1	1		1	1	~	\	<	<	<	Windows size (✓ or 🗙)
			4			-	1	/	1	(4	۲	<	<	<	Windows - template depth & diagonal (✓ or 🗙) Windows - template
			4			1	[1	١	1	1	4	<	<	〈	Windows - template powder coated (v or x)
			3			1	1	1	1	1	1	1	1		1	Loft & Kitchen platform required ? (Yes or No)
					[\	1	1	1)	-	1	١	١	١	\	Loft & Kitchen platform provided (v or x or NA)
			•	1		9		1)	1)	١))	Loft & Kitchen platform slope (v or x)