Quality Control Check Repot. Stage: After Plastering (Apartments)

Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Flat No.
Stop further work. Submit ATR on QC report Stop further work. Proceed with work after s Proceed with further work only after making of the proceed with further work. ATR not required		0.	Tradho	M. Tégassidher	VISTA HOMES	5-109
eport to QC team. Proceed the submitting ATR on ting corrections pointedired.	MD Sign	27674	Sign	Sign	Project	Other
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck Stop further work. Proceed with work after submitting ATR on QC report to QC team Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.		Report filed and signed by PM?	1- Joully	Q4	VISTA HOMES	
t by QC. n. ATR not required.	For filling	ed by PM?	Date	Date	Phase	Sl. No.
	☐Yes ☐No	√Yes □No	4111188	23/11/17	1	28486

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed
- before starting painting, tiling & flooring.

Plastering Check.

Notes:

- Mark v for correct or minor mistake which does not require correction Mark X for minor mistake that requires minor correction.

 Mark X for major mistake that requires correction by replacement or re-fixing. Mark X X for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Plastering must be 3mm margin for luppum work. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have ½"grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Rer	15	14	13	12	=	0.1	9	∞	7	6	5	4	w	2	<u> </u>	S No
Remarks	Other	Other	Kitchen	Utility-/balcony3	Utility / balcony-2	Htilty / balcony 1	Labby-1-	Dining	Drawing	Toilet3	Bedroom 3 (46)	Toilet 2 (CT)	Bedroom 2 (KB)	Toilet 1 (Mで)	Bedroom 1 (代島)	Room
			<	1	<u> </u>	〈	1	<	<	1	て	<u> </u>	<	<	<	Skirting Provision (• or ×)
			-	1	<	}	1	1	ς		~	<	<	<	<	Finishing around door frame (• or ×)
			く	1	<]	١	<u>ح</u>	<	•	~	<	<	<	5	Beams & columns finishing (• or ×)
			1/	1	-	J		/	1	1	\	t	-		Ş	Finishing of lofts (v or x)
			<	1	く	<	1	(۷,	\	~	2	4	۷ .	<	Electrical junctions finishing (• or ×)
			<	- a	l	1	1	\	}	ļ	۷	<	<	<u> </u>	<	Window check ⁶ (v or x)
			7		1	3	1		<u></u>	-	\	<	1	1	<u> </u>	Tiles provision (✓ or 🗙)
			<	-	[1	Ì		1	-	1	<	1	<	1	Sink provision & size (✓ or 🗙)
			1	1	र	{	1	1	5	-	<	<	<	<	<	Grooves for door frames (✓ or 🗙)
				1	ſ	1	1	1	1	Ŋ	١	1	1	١	ſ	Balcony & terrace sill top finishing(• or ×)
			1		<)	}	[)		-	۷,		Ç	ſ	Screeding in bathroom & utility (v or x)
				l	<)	1))	1	1	<)	<	1	Screeding in 6" above FFL? (v or x)