Quality Control Check Repot. Stage: After Plastering (Apartments)

- D1 ^					
Tat INO.	301	Other		SI. No.	33330
Company	(dan) MSS	Project	Sev	Phase	[A]
Prepared by	P Son kuner Sign		Pldy	Date	2/4/19
Project Manager	K "Tristation	Sign	P	Date	2/4/19
Previous stage report no.	no.	78978	Report filed and signed by PM?	d by PM?	□Xes □No
Checked By MD on		MD Sign		For filling	☐Yes ☐No
Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	port to QC team. Proceer submitting ATR on ing corrections pointed red.	eed only after recheck! QC report to QC team! out in the QC report.	by QC. ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the apartment.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark v for correct or minor mistake which does not require correction
 Mark x for minor mistake that requires minor correction.

 Mark x for major mistake that requires correction by replacement or re-fixing.

 Mark x x for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. <u>Plastering must be 3mm margin for luppum work</u>. Tolerance ¼". Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.