Quality Control Check Repot. Stage: After Plastering (Villas)

| | | | 4 | | |
|---|--|---|--|---------------------------|------------|
| Villa No. | 156 | Stage | , | Sl. No. | 34096 |
| Company | Nilgiri - Estatas Project | Project | Nilgini - Estates | Phase | ति |
| Prepared by | C. RAJESH | Sign | ENCE | Date | 27 07 19 |
| Project Manager | 5 | Sign | 3.30 | Date | 22/07/19 |
| Previous stage report no. | no. | 33667 | Report filed and signed by PM? | d by PM? | √Yes □No |
| Checked By MD on | | MD Sign | | For filling | ☐ Yes ☐ No |
| Recommendation: Stop further work Stop further work Proceed with furt Proceed with furt | Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required. | port to QC team. Procester submitting ATR on ing corrections pointedired. | eed only after recheck b QC report to QC team. I out in the QC report. / | by QC. ATR not required. | |

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark X for major mistake that requires correction by replacement or re-fixing.

 Mark X X for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolcrance 1/4".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

14

Terrace/balcony 2

Head room

12

Lobby 2

Lobby 1

Toilet 4

Bedroom 4

Drawing

Toilet 3

Toilet 2 Bedroom 3

Ferrace / balcony l

18

19

Utility Other

Remarks

15 16

į

Kitchen

2

Toilet 1 Bedroom 2

51

Bedroom

S No

Room

Skirting Provision

Balcony & terrace sill top finishing ¹⁰(✓ or ×)

Screeding in bathroom

Screeding in 6" above

& utility (or x)

FFL? (• or ×)

(or X)

Quality Control Check Repot. Stage: After Plastering (Villas)

| | Remarks: | Plastering and finishing of chajjas (v or x) | Plastering quality of parapet walls (✓ or 🗙) | Is plastering of compound wall and villa external walls 6" below FFL of setbacks? | Plastering of compound wall & gate pillars (v or x) | Miscellaneous check Overall quality of plastering? |
|--|----------|---|--|---|--|--|
| | | | | Yes No | 5 | Good Avg. Bad |