## Quality Control Check Repot. Stage: After Plastering (Villas)

			7		
Villa No.	05	Stage		Sl. No.	31916
Company	S0V(LLP)	Project	201	Phase	X
Prepared by	S. Kuldrep	Sign	Shridens	Date	01111118
Project Manager	K. Pulshotham Sign	Sign	X	Date	31/11/112
Previous stage report no.	no.	78918	Report filed and signed by	d by PM?	Yes No
Checked By MD on		MD Sign		For filling	Yes No
Recommendation:	Submit ATP on OC	mort to OC team Drog	eed only often recheal, t		
Stop further work.  Stop further work.	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck!  Stop further work. Proceed with work after submitting ATR on QC report to QC team.	eport to QC team. Proceed ter submitting ATR on	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.	y QC.	
Proceed with furth	er work only after mak	ing corrections pointed	Proceed with further work only after making corrections pointed out in the QC report. ATR	ATR not required.	
Proceed with furth	Proceed with further work. ATR not required.	ired.			

## Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

### Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

  Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Tolerance 1/4".
- Provision of tiles in buthrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- 10. Sill top must be of uniform thickness, correct height, at one level & without broken edges.

		•	
111	7900	,	
ŀ			
	7	,	

	Ren	19	18	17	16	15	14	13	12	11	10	9	8	7	6	Ŋ	4	ယ	2	1	S No
	Remarks	Other	Utility	Kitchen	Portico	Head room	Terrace/-baleony-2	-Terrace / balcony 1	Lebby-2-	Lobby-1 formity lange	Dining	Drawing	Toilet 4	Bedroom 4	Toilet 3 とて	Bedroom 3 4.B		n 2	Toilet 1 ਕੁਰ	Bedroom l උා ප	Room
				ς.	J	۲,	1	ζ	}	7	1	۲	1	,	<	y	5	ζ	5	5	Skirting Provision ( • or ×)
		30		}	1	ζ.		1	9.79	1	•	5	ĺ	1		ζ,	5	5	ζ	5	Finishing around door frame ( v or x)
				<	1	ζ.	•	<	BALL STORMS	<		\	į	1	<u> </u>	5	1	ζ	5	(	Beams & columns finishing ( v or x)
					1	•••	1	-	ì	1	1	ţ	(	1	1	}	1	١	1	ţ	Finishing of lofts ( v or x)
				ζ	J	۲	1	1	Ì	ς	!	ς_	1	1	<	۲,	<i>&gt;</i>	5	5	5	Electrical junctions finishing ( • or ×)
				<	(	ς	1	4	Į,	5		ς.	ſ	}		ζ	ζ	?	7	ζ	Window check ( v or x)
eg - (An ang ang ang ang ang ang ang ang ang an				<	{	}	١	}	•	1	1	١	1	1	1	1	7	-	5		Tiles provision ( • or ×)
				5	١	Ì			1	1	•	1	(	ī	1	ſ	)		}	-	Sink provision & size ( • or ×)
	8			at a second	1	<	1	<	,	-	1	<	1		7	5	<	5	5	5	Grooves for door frames ( v or x)
				J	[	}	ţ	1	3	(	1	!	ı	1	1	,	I	-	*****	1	Balcony & terrace sill top finishing <sup>10</sup> ( • or ×)
				)		1	1	4	1	1	}	1	)	,	V		5	)	٢	1	Screeding in bathroom & utility ( v or x)
						1	1	,	1	1	1	1	}	j	ς.	1	2	4	5	1	Screeding in 6" above FFL? (v or x)

# Quality Control Check Repot. Stage: After Plastering (Villas)

	Remarks:	Plastering and finishing of chajjas (✓ or X)	r lastering quanty of parapet walls ( $\checkmark$ or $\times$ )	The training of compound wall and villa external walls 6" below FFL of setbacks?	Is plastering of compound wall & gate pillars ( v or x)	Overall quality of plastering?	Miscellaneous check
	_ <		<b>\</b>	Yes No	<	Good ☐ Avg. ☐ Bad	