Checked By MD on Block No Recommendation: Project Manager Prepared by Company Previous stage report no. Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC Quality Control Check Repot. G. Sarwar siander Sezons unstruction 00 MD Sign Sign Project Sign 1 31328 Stage: Before Casting Plinth Beam (Villas) Sys I golum Survivo Report filed and signed by PM? Serens farms Alice of the second Date Phase SI. No. Date For filling V Yes 10/80 09/01/19 Yes 32599 1 \bar{z} L No

Plinth Beam Check

Stop further work. Proceed with work after submitting ATR on QC report to QC team

Proceed with further work only after making corrections pointed out in the QC report. ATR not required.

Proceed with further work. ATR not required.

- Inspection should be done before casting of plinth beam.
- Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark
- Prepare plinth beam Dimensions Check Plan as follows:
- Show outer dimensions. (Tolerance 2")
 Show length and width of plinth beams (Tolerance 1")
- Print an A3 size plan.
- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it. Project managers must make pedestal/column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.
- Plinth Beam Dimensions Check Plan enclosed? ∐Yes Z

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

ng?	Good Avg. Bad Yes No,A Good Avg. Bad Good Avg. Bad Yes No No Yes No Correct Needs correction
Brackets for elevation features provided?	Yes No NA
Level marking at 2' above FFL is made?	☐Yes ☐No
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Correct Needs correction
Pedestal/column0 - self check report attached?	☐Yes ☐Ño
Remarks:	

Plinth Beam Steel check.

Notes:

- Mark v for correct or minor mistake which does not require correction
 Mark x for minor mistake that requires minor correction.
 Mark x x for major mistake that requires correction by replacement or re-fixing.
 Mark x x for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7. Depth and w	6. Covering blo	5. Steel Check		3. Steel Check	2. Steel Check			SNo	ACC MARKET
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods		Item	
	<	ς .	<	,	<		ζ	(• or ×)	Quantitative Check	
	☑ Good ☐ Avg. ☐ Bad	☐Good ☐Avg. ☐ Bad	Good Avg. Bad	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☑Good ☐ Avg. ☐ Bad	☑ Good ☐ Avg. ☐ Bad	(Good / Avg. / Bad)	Qualitative Check	