### Recommendation: Checked By MD on Previous stage report no Project Manager Block No Prepared by Company Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC Quality Control Check Repot. A GO.H Lakin Hussain V. Sanketh 0 MD Sign 31270 Sign Sign Project Stage: Before Casting Plinth Beam (Villas) AVR Gulmoha Report filed and signed by PM? 4. Sx 15.4 For filling Date Sl. No. Date Phase $\sqrt{Y}$ es 27/10/18 27/10/18 Yes 31867 JNo No

### Plinth Beam Check.

Stop further work. Proceed with work after submitting ATR on QC report to QC team.

Proceed with further work only after making corrections pointed out in the QC report. ATR not required

Proceed with further work. ATR not required.

- Inspection should be done before casting of plinth beam.
  Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark.
- Prepare plinth beam Dimensions Check Plan as follows:
- Show outer dimensions. (Tolerance 2")
- Show length and width of plinth beams (Tolerance 1")
- Print an A3 size plan.
- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

# Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

	the villa.	Remarks: Nort: Much not levelled Proposity at inside word	Pedestal/column0 – self check report attached?	Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Level marking at 2' above FFL is made?	Brackets for elevation features provided?	Alignment of beams on outer side?	Quality of Bracing Provided?	Have rods for staircase slab been provided?	Quality of centering, rod bending and concreting?
		and sitbacks of	Yes No	Correct Needs correction	√Yes □No	☐ Yes ☐ No ☑NA	✓ Good ☐ Avg. ☐ Bad	Good Avg. Bad	∏Yes	Good Avg. Bad

## Plinth Beam Steel check.

Notes:

- Mark v for correct or minor mistake which does not require correction
   Mark X for minor mistake that requires minor correction.
   Mark X for major mistake that requires correction by replacement or re-fixing.
   Mark X X for major mistake that cannot be corrected.
- Columns overlapping length should be 45 to 50 D.

# Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7.	6.	5.	4.	3.	2.	<b></b>	S No
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
		`	<b>~</b>	<	~	7	4	Quantitative Check ( • or ×)
	☐ Good ☑ Avg. ☐ Bad	Good Avg. Bad	Good Avg. Bad	☑ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☑Good ☐ Avg. ☐ Bad	Good ☐ Avg. ☐ Bad	Qualitative Check (Good / Avg. / Bad)