Quality Co
ntrol Cl
Quality Control Check Repot.
Stage:
Before
Stage: Before Casting Slab (Villas)
(Villas)

Block No Company Company Prepared by Project Manager Previous stage report no. Checked By MD on Recommendation: Recommendation: Responsible ATR on OC report to the stage of the s	Slab No. Project Sign Sign MD Sign OC team. P.	Report filed and signed by PM?	SI. No. Phase Date Date 7? For filling	16 09 19 16 09 19 16 09 19 18 09 19 19 19 19 19 19 19 19 19
	Sign	Tivlined Rumal	Date	16/09/19
*	Sign	()	Date	16/07/19
į.		Report filed and signed by PN	1?	Yes No
Checked By MD on	MD Sign		For filling	Yes No
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR n Proceed with further work. ATR not required.	o QC team. Pomitting ATR	oceed only after recheck by Quon QC report to QC team. Ited out in the QC report. ATR	not required.	

- Notes: Slab Check. Inspection should be done before casting of slab at each stage i.e. when the slab is ready for casting. Prepare Slab Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")
 Show inner dimensions of ducts. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.
- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

Slab Dimensions Check Plan enclosed?	
Actual ht: Within tolerance of ½"?	$\frac{1}{2}$ "? \square Yes \square No
Actual ht: Within tolerance of ½"?	1/2"? Yes No
Specified wd: Actual wd: Within tolerance of ½"?	1/2"? Yes No
Actual: Within tolerance of 1/4"?	1/4"? Yes No
Actual:	\ \tau \

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

A THE STATE OF THE	
	Remarks:
☐ Correct ☐ Needs correction	Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)
☐ Good ☑ Avg. ☐ Bad	Shuttering leveling?
☐ Good ☑ Avg. ☐ Bad	Alignment of beams on outer side?
☐ Good ☑ Avg. ☐ Bad	Quality of Bracing Provided?
□Yes ☑No	18 extension to beam bottom runners on outer side provided?
☐ Good ☑ Avg. ☐ Bad	Quality of centering, rod bending and concreting!
	Quality of centering, rod bending and concreting.

Slab Steel check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

 Mark X for major mistake that requires correction by replacement or re-fixing.

 Mark X X for major mistake that cannot be corrected.
- Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. S

Stage: Before Casting Slab (Villas)

	imbrave.	Remarks: Mod bending to be	Rema
Good Avg. Bad	e in the second	16. Steel check – slab extensions/ joints	
Good Avg. Bad	وسيقر المس	15. Steel check – floating columns	
☐ Good ☑ Avg. ☐ Bad	۲,	14. Electrical Conducting	
Good Avg. Bad	۲,	13. Steel Check - Column steel overlapping length and cranking	
☐ Good ☑ Avg. ☐ Bad	< .	12. Covering blocks for slab	
Good Avg. Bad	ν.	11. Steel Check - Slab Extra Bars	
☐ Good ☑ Avg. ☐ Bad	<	10. Steel Check – Slab cranking & chairs	
Good Avg. Bad	ζ.	9. Steel Check - Slab spacing of bars	
☑ Good ☐ Avg. ☐ Bad		8. Steel Check - Slab size of bars	
Good Avg. Bad		7. Depth and width of beams	
Good Avg. Bad	ζ.	6. Covering blocks for beams	
☐ Good ☐ Avg. ☐ Bad	ζ,	5. Steel Check - Beams Bearing	
Good Avg. Bad	ζ.	4. Steel Check - Beams Overlapping & Cranking	
Good Avg. Bad	<.	3. Steel Check - Beams Extra Bars	
Good Avg. Bad	<	2. Steel Check - Beam size of bars	
Good Avg. Bad		1. Steel Check - Beam no of rods	
Qualitative Check (Good / Avg. / Bad)	Quantitative Check (or x)	S _k No Item 1	Š