## Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	rroject Manager		В	Villa No.
		10.	Pueshottem	Sixuldeep	SON (LLP)	
	MD Sign	30732	Sign	Sign	Project	Stage
		Report filed and signed by PM?	*	Buders	SoV	
	For filling	ed by PM?	Date	Date	Phase	SI. No.
	☐Yes ☐No	□Yes □No	2002/80/80	08/08/2018	[X	31094

Inspection should be done after:

- brickwork & 2 coats plastering is completed after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

## Plastering Cheek.

- Mark ➤ for correct or minor mistake which does not require correction

  Mark ➤ for minor mistake that requires minor correction.

  Mark ➤ x for major mistake that requires correction by replacement or re-fixing.

  Mark ➤ X for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance 14".

- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance, 1")
- All doors frames should have '2"grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Page 2 of

## Quality Control Check Repot. Stage: After Plastering (Villas)

Remarks:	Is plastering of compound wall and villa external walls 6" below FFL of setbacks?  Plastering quality of parapet walls ( v or x)	Miscellaneous check  Overall quality of plastering?  Plastering of compound wall & gate pillars ( v or x)
	Yes No	□ Good ☑ Avg. □ Bad