XYes □ No

812/18

∏Yes ∏No

29236

Quality Control Check Repot. Stage: After Column Casting (villas)

Quality of centering, rod bending and concreting.		
Quality of centering, rod bending and concreting?		Good Avg. Bad
Quality of starters?		Good Avg. Bad
Number and size of honey combs?		☐ High [VMedium. ☐ Low
Are the honey combs is slab and columns packed?		☐ Good [YAvg. ☐ Bad
Number of beams that are sagging, bulging, caved or deflected in the slab by more than 1"	ın 1"	, 1
Have 6 cubes each for columns and slab casted and numbered for testing?		\[\frac{\frac{1}{2}\text{Yes}}{\text{No}}\] No
Remarks:		
Bunds for curing made on slab?	Yes No	7.187
Bund size is less than 100 sft?	Yes No	ての
Drum (200 lts) provided for curing?]Yes ☑No	
Gunny bags used for column curing?	☑Yes □No	
Distance of tap from furthest distance that requires curing. (max permitted 100')	30.00	
Frequency of curing in number of times a day (enquire from labourers)	2 times	
Is the pressure in the curing pipe more than 15' head?	☐Yes □No	
Quality of infrastructure for curing.	ਔ Good ☐ Avg. [Bad
Remarks:		

Columns height, plumb, steel & level marking check.

- Mark \checkmark for correct or minor mistake which does not require correction.

 Mark \times for minor mistake that requires minor correction.

 Mark \times for major mistake that requires correction by replacement or re-fixing.

 Mark \times X for major mistake that cannot be corrected.

 Tolcrance: Plumb 0.25°.

Circle actual height of columns if level differs from specified height by more than 1".

20.	19.	18.	17.	16.	15.	14.	13.	12.	11.	10.	9.	œ	7.	6.	5.	4.	3.	2.	1.		S No
			2000 E		100000000000000000000000000000000000000	80	40	05	7	ヤー	4	(Y	ر ب	<u></u>	84)	7.	K3	42	9		Col No.
						CI	CP	CL	CI	C1	CY	(۲	2	21	()	3	3	CI	0		Col type
						Sharcox	Showers	8 7 1 × 10	13/14:00	21.711	8.71.1	8.4.1.	ウリンティ	0-21 C	13.711.	8. 41/21	8,411,4	11/4- S	1914.8	Spec.	Heigh
		9				Shewweres	Sharare	10.81	A9_	Ø7. ∞5 +	8 81	8.51	14.20	8.8"	22.2	8,50	81:41	17. -	1.4.8°	Actual	Height in ft
						<	5	5	5	ζ.	5	<,	< .	ς,	<	<	5	5	<u> </u>	No of rods	Steel (
						<	<	<	<	<	5	\	Κ,	<,	ς _.	5	<	5	<	Size of rods	Steel (or x)
		Comment				<	<	<	5	<	<	<	4	*	Κ.	<	メ	5	<		Honeycombs
						<	<	5	<	<	. \		_	<	<	<	<	<	<	Side 1	Plumb
					i.	<	5	5	_	<	5	<	5	5	<	<	5	<	<	Side 2	Plumb (v or x)
Yes No	☐ Yes ☐ No	☐ Yes ☐ No						İ	╽┌	l				Yes No			ľ			column?	Reference level