	/	,	
j	,	/	
		/	

	Quality Control Check Repot.	eck Repot.	Stage: Before Casting Slab	b (Villas)	
Block No	115	Slab No.	03	SI. No.	32475
Company	VOC (LLP)	Project	VOC	Phase	1
Prepared by	S. Kuldrep	Sign	engling	Date	27/12/18
Project Manager	A. Susush	Sign	Ç	Date	24/12/18
Prcvious stage report no.	10.	32375	Report filed and signed by PM	17?	Yes No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Stop further work. Proceed with furthe	Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck l Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	QC team. Pr mitting ATR rrections poin	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required.	not required.	

Slab Check.

Notes:

- Inspection should be done before casting of slab at each stage i.e. when the slab is ready for casting.
 Prepare Slab Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
 Show length and width of balconies (Tolerance 1")
 Show inner dimensions of ducts. (Tolerance 1")
- Show location of sunken slab. Print an A3 size plan.
- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension

Slab Dimensions Check Plan enclosed?	ed?		Yes No	No		O I E
Staircase - mid landing1	Specified ht:	1	Actual ht:	q	Within tolcrance of 1/2"?	☐ Yes ☐ No
Staircase - mid landing 2	Specified ht:	1	Actual ht:	1	Within tolerance of 1/2"?	□Yes □No
Staircase width	Specified wd:	1	Actual wd:	1	Within tolerance of ½"?	☐Yes ☐No
Staircase slab thickness	Specified:	1	Actual:	Į.	Within tolerance of 1/4"?	☐ Yes ☐ No

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	☐ Good ☐ Avg. ☐ Bad
18"extension to beam bottom runners on outer side provided?	☐Yes ☑No
Quality of Bracing Provided?	☐ Good ☑ Avg. ☐ Bad
Alignment of beams on outer side?	☐ Good ☐ Avg. ☐ Bad
Shuttering leveling?	☐ Good ☑ Avg. ☐ Bad
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Correct Needs correction
Remarks:	

Slab Steel check.

- Notes:
- Mark or for correct or minor mistake which does not require correction

 Mark X for minor mistake that requires minor correction.

 Mark X for major mistake that requires correction by replacement or re-fixing.

 Mark X X for major mistake that cannot be corrected.

 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

		(v or X)	(Good / Avg. / Bad)
<u></u>	Steel Check - Beam no of rods	5	
2.	Steel Check - Beam size of bars	ζ	☐ Good ☐ Avg. ☐ Bad
3.	Steel Check - Beams Extra Bars	<	Good Avg. Bad
4.	Steel Check - Beams Overlapping & Cranking		☐Good ☐ Avg. ☐ Bad
5.	Steel Check - Beams Bearing	<	☐ Good ☐ Avg. ☐ Bad
6. (Covering blocks for beams		☐ Good ☐ Avg. ☐ Bad
7. I	Depth and width of beams	<	☐ Good ☑ Avg. ☐ Bad
8.	Steel Check - Slab size of bars		Good Avg. Bad
9. §	Steel Check - Slab spacing of bars	ζ.	☐ Good ☐ Avg. ☐ Bad .
10. S	Steel Check - Slab cranking & chairs		☐ Good ☐ Avg. ☐ Bad
11. S	Steel Check - Slab Extra Bars		Good Avg. Bad
12.	Covering blocks for slab		Good Avg. Bad
13. S	Steel Check - Column steel overlapping length and cranking	•	☐ Good Avg. ☐ Bad
	Electrical Conducting	<	☐ Good ☑ Avg. ☐ Bad
15. S	Steel check – floating columns	THE PARTY OF THE P	☐Good ☐ Avg. ☐ Bad
16. S	Steel check – slab extensions/joints	<	☐ Good ☑ Avg. ☐ Bad
Remarks:		The state of the s	