Quality Control Check Repot. Stage: Before C	Control Check Repot. Stage: Before Casting Slab (V		Quality
			/ Control
Stage: Before C	Stage: Before Casting Sla		Check Repot.
Before C	Before Casting Sla	200	Stage:]
	asting Sla		Before C

Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Block No
ecommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck lystop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	3	10.	A. C. Bresh	V. Samboth	Voc (LLP) Project	= 7
o QC team. Pomitting ATR	MD Sign	31880	Sign	Sign	Project	Slab No.
ATR		Report filed and signed by PM?	Ç	くる。大人	You	03
2C. R not required.	For filling	M?	Date	Date	Phase	Sl. No.
	Yes No	✓ Yes □No	c5 n l/8	05/11/18	1	31980

Slab Check.

Notes:

- Inspection should be done before casting of slab at each stage i.e. when the slab is ready for casting.
 Prepare Slab Dimensions Check Plan as follows:

 Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")
 Show inner dimensions of ducts. (Tolerance 1")
 Show location of sunken slab.
 Print an A3 size plan.

- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted.

 Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

Slab Dimensions Check Plan enclosed?	id?	Collection	Yes No	No	C HEATHERT CANADA AVIET COLOT MANAGEMENT	
Staircase - mid landing1	Specified ht:	1	Actual ht:	1	Within tolerance of 1/2"?	☐Yes ☐No
	2		A _4		İ	TVac TNA
Staircase - mid landing 2 .	Specified ht:	•	Actual ht:	1	Within tolerance of ½"?	Yes No
Staircase width	Specified wd:	1	Actual wd:	-	Within tolerance of 1/2"?	☐Yes ☐No
Staircase slab thickness	Specified:		Actual:		Within tolerance of 1/4"?	∏Yes ∏No

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

		Remarks:	Column steel overlapping and cranking? (overlapping length should be 15 to 25.7)	Shuttering leveling?	Alignment of beams on outer side?	Zuanty of Diacing From the 14-9	Onelte of Brooing Provided?	18" extension to beam bottom runners on outer side provided?	Quality of centering, rod bending and concreting? Quality of centering, rod bending and concreting?
				✓ Correct Needs correction	Good Avg. Bad	Good Avg. ☐ Bad	Good Avg. Bad	L Yes KNO	Good Avg. Bad

Slab Steel check. Notes:

- Mark v for correct or minor mistake which does not require correction
 Mark X for minor mistake that requires minor correction.
 Mark XX for major mistake that requires correction by replacement or re-fixing.
 Mark XX for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

				Remarks:
	✓ Good ☐ Avg. ☐ Bad	<	Steel check – slab extensions/ joints	16.
	☐ Good ☐ Avg. ☐ Bad	•	Steel check – floating columns	15.
	√Good Avg. Bad	~	Electrical Conducting	14.
	Good Avg. ☐ Bad	7	Steel Check - Column steel overlapping length and cranking	13.
	Good Avg. Bad	~	Covering blocks for slab	12.
	Good DAvg. DBad	~	Steel Check - Slab Extra Bars	11.
	Good Avg. Bad	√ ,	Steel Check – Slab cranking & chairs	10.
500	☐ Good ☑ Avg. ☐ Bad	~	Steel Check - Slab spacing of bars	9.
	✓ Good Avg. Bad	<	Steel Check - Slab size of bars	
	Good ☐ Avg. ☐ Bad	~	Depth and width of beams	7.
	☑Good ☐ Avg. ☐ Bad	~	Covering blocks for beams	6.
	Good Avg. Bad	✓	Steel Check - Beams Bearing	5.
	☐ Good Avg. ☐ Bad	۷.	Steel Check - Beams Overlapping & Cranking	.4
	Good Avg. Bad		Steel Check - Bcams Extra Bars	3.
	Good Avg. Bad		Steel Check - Beam size of bars	2.
		<u> </u>	Steel Check - Beam no of rods	1.
88	Qualitative Check (Good / Avg. / Bad)	Quantitative Check	Item	SZO
•				