Q	Quality Control Check Repot.	Stage: Before Casting Slab (Villas)	(Villas)	
Block No	199 Slab No.	0	SI. No.	र्राव १३०३
Company	Nilgini Estates Project	Nilgini Estates	, a	, <del>L</del>
Prepared by	S. Sun & Was Sign	C		02/02/18
Project Manager Walkhi	Sign	PA varvoor	Date	08/08/18
Previous stage report no.	0 K Z D D	Report filed and signed by PM?		S No
Checked By MD on	MD Sign		For filling	Yes No
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.	IR on QC report to QC team. with work after submitting AT nly after making corrections por TR not required.	Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not proceed with further work. ATR not required.	not required.	
Proceed with further Work. F	Y K HOL reduired.			

Slab Check.

- Inspection should be done before easting of slab at each stage i.e. when the slab is ready for easting.
   Prepare Slab Dimensions Check Plan as follows:

   Show outer dimensions of slab. (Tolerance 2")

- b. Show length and width of balconies (Tolerance 1")
  c. Show inner dimensions of ducts. (Tolerance 1")
  d. Show location of sunken slab.
  e. Print an A3 size plan.
  Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted.
  Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted.

A Circle each correct dimension with oreen colour. Circle each incorrect dimension with red colour and mention actual dimension liext to it.	colour. Circle each	incorrect d	imension with re	d colour and	mention actual dimension liext to it.
Slab Dimensions Check Plan enclosed?	12	9	☐Yes ☐No	No	
Staircase - mid landing1	pecified ht:	V- V-	Actual ht: 45		Within tolerance of 1/2"? Yes No
		2	1	C	Vac No
Staircase - mid landing 2	Specified ht:	)	Actual ht:	)	Within tolerance of ½; / Lies Live
	1				Ves No
Staircase width	Specified wd:	10.0	O-c Actual wd: O-O Within I	10-0	Within tolerance of 72 : Fig. 103
			A chia].		Within tolerance of 1/4"? \ \ \ Yes \ \ No
Staircase slab thickness	ъресплеа:	1	Actual.		a de la companya de l

## Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	Good Avg. Bad
18"extension to beam bottom runners on outer side provided?	☐Yes ☐No
Quality of Bracing Provided?	☐ Good ☐ Avg. ☐ Bad
Alignment of beams on outer side?	☐ Good [☐ Avg. ☐ Bad
Shuttering leveling?	☐ Good [☐ Avg. ☐ Bad
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Correct Needs correction
Remarks: A Centering and Rud Bending works was Ne	YOU HON KON

## Slab Steel check. Notes:

- Mark v for correct or minor mistake which does not require correction
   Mark X for minor mistake that requires minor correction.
   Mark X for major mistake that requires correction by replacement or re-fixing.
   Mark X X for major mistake that cannot be corrected.
   Columns overlapping length should be 45 to 50 D.

## Quality Control Check Repot. Stage: Before Casting Slab (Villas)

			Remarks:
Good Avg. Bad		Steel check - slab extensions/ joints	16.
☐ Good ☐ Avg. ☐ Bad	)	Steel check - floating columns	15.
Good Avg. Bad	(	Electrical Conducting	14.
☐ Good ☐ Avg. ☐ Bad		Steel Check - Column steel overlapping length and cranking	13.
Good Avg. Bad	<	Covering blocks for slab	12.
☐ Good ☐ Avg. ☐ Bad	ς .	Steel Check - Slab Extra Bars	11.
	ζ	Steel Check - Slab cranking & chairs	10.
Good Avg. Bad	7	Steel Check - Slab spacing of bars	9.
Good Avg. Bad	ς .	Steel Check - Slab size of bars	8.
Good Avg. Bad	ζ.	Depth and width of beams	7.
☐ Good ☐ Avg. ☐ Bad	(	Covering blocks for beams	6.
☐ Good ☐ Avg. ☐ Bad	<	Steel Check - Beams Bearing	5.
Good Avg. Bad	<	Steel Check - Beams Overlapping & Cranking	4.
Good Avg. Bad	ζ.	Steel Check - Beams Extra Bars	3.
Good -Avg. Bad		Steel Check - Beam size of bars	2.
Cicod Avg. Bad	ζ.	Steel Check - Beam no of rods	-
Qualitative Check (Good / Avg. / Bad)	Quantitative Check (✓ or ×)	Item	oN S