Ouality
Control
Quality Control Check Repot.
 Stage: Before Casting Slab (Villas)
e Casting S
Slab (Vil

Recommendation: Stop further work. Submit ATR on QC report Stop further work. Proceed with work after s Proceed with further work only after making Proceed with further work. ATR not required	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Company	Block No
bmit ATR on QC report to oceed with work after sub vork only after making covork. ATR not required.	district of the second	•		c. kuldesp	voc (LLP)	124
QC team. Pr mitting ATR trections poin	MD Sign	31934	Sign	Sign	Project	Slab No.
ecommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.		Report filed and signed by PM?	Ç	Smales	\o (_	0)
C. not required.	For filling	M?	Date	Date	Phase	SI, No.
	Yes No	LYes No	01/12/18	81/21/10	Sept. 1	3225H

Slab Check.

Notes:

- Inspection should be done before easting of slab at each stage i.e. when the slab is ready for easting.
 Prepare Slab Dimensions Check Plan as follows:

 Show outer dimensions of slab. (Tolerance 2")
 Show length and width of balconies (Tolerance 1")
 Show inner dimensions of ducts. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.
- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted.

 Circle cach correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

Slab Dimensions Check Plan enclosed?	ed?		Yes No	No		
Staircase - mid landing1	Specified ht:	21-0"	21-0" Actual ht:	21011	Within tolerance of 1/2"?	Yes No
Staircase - mid landing 2	Specified ht:	1	Actual ht:	1	Within tolerance of 1/2"?	Yes No
Staircase width	Specified wd:	9-2:	9'-2" Actual wd: 9'-2"	9-2"	Within tolerance of 1/2"?	Yes No
Staircase slab thickness	Specified:	21	5" Actual:	411	Within tolerance of 1/4"?	Yes No

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	☐ Good ☑ Avg. ☐ Bad
18"extension to beam bottom runners on outer side provided?	☐ Yes ☑No
Quality of Bracing Provided?	Good Avg. Bad
Alignment of beams on outer side?	Good Avg. Bad
Shuttering leveling?	☐Good ☐Avg. ☐Bad
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	☐ Correct ☐ Needs correction
Remarks:	

Slab Steel check. Notes:

- Mark \vee for correct or minor mistake which does not require correction Mark \times for minor mistake that requires minor correction.

 Mark \times for major mistake that requires correction by replacement or re-fixing.

 Mark \times X for major mistake that cannot be corrected.

 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

			Remarks:
☑ Good [<	Steel check – slab extensions/joints	16.
☐ Good [Avg. [<	Steel check – floating columns	15.
Good Avg.	<	Electrical Conducting	14.
Good Mayg.	<u> </u>	Steel Check - Column steel overlapping length and cranking	13.
☑ Good [Covering blocks for slab	12.
Good Avg. Bad		Steel Check - Slab Extra Bars	11.
Good ☐ Avg. ☐ Bad		Steel Check – Slab cranking & chairs	10.
Good Avg.		Steel Check - Slab spacing of bars	9.
Good Avg.		Steel Check - Slab size of bars	
Good Avg.	<	Depth and width of beams	7.
Good Avg. Bad	<	Covering blocks for beams	6.
☐ Good ☐ Avg.	(Steel Check - Beams Bearing	5.
Good Avg.	(Steel Check - Beams Overlapping & Cranking	.4
Good Avg.		Steel Check - Beams Extra Bars	, w
☐ Good Avg.	ς	Steel Check - Beam size of bars	2.
Good ☐ Avg. ☐	<	Steel Check - Beam no of rods	
Qualitative Check (Good / Avg. / Bad	Quantitative Check (• or *)	Item	U No
			2