	Quality Control Check Repot.
	alit
-	V (
	čon
	itro
	7
	The
	ck
	Re
	ÖĞ
	ť.
	St
	20
	e:
	<u> ef</u>
I),TO
	Ö
	ast
I	gui
I	
I	E
	H
	Bee
	Ħ
I	Stage: Before Casting Plinth Beam (Villas)
	illa
	Ö

Report filed and signed by PM?	Block No Company Prepared by Project Manager	Nilgian States Project Sign Ninkly Sign Sign	Milgian Estadan Phase Milgian Estadan Date Milgian Estadan Date	\$11/4/118 TII: 07/668
t no.	Project Manager	Modhu Sudah Sign	On MAN Date	राजि।
MD Sign For filling	Previous stage report no.	28803	Report filed and signed by PM?	Yes No
	Checked By MD on	MD Sign	For filling	☐ Yes ☐ No

Plinth Beam Check. Notes:

- 4. 2 Inspection should be done before casting of plinth beam.

 Yellow ename! paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark. Prepare plinth beam Dimensions Check Plan as follows:

 a. Show outer dimensions. (Tolerance 2")

 b. Show length and width of plinth beams (Tolerance 1")

 c. Print an A3 size plan.

 Circle cach correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

 Project managers must make pedestal/column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.

mens	
m Dimensions Check Plan enclosed?	
□Yes □No	

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Quality of centering, rod bending and concreting?	
Given Summaning	Coon Avg. Dan
Have rods for staircase slab been provided?	Yes No
Quality of Bracing Provided?	☐ Good ☐ Avg. ☐ Bad
Alignment of beams on outer side?	☐ Good ☐ Avg. ☐ Bad
Brackets for elevation features provided?	□Yes □No □NA
Lovel marking at 2' above FFL is made?	∑·Yes □No
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	☐ Correct ☐ Needs correction
Pedestal/column0 – self check report attached?	Yes No
Remarks:	

Plinth Beam Steel check. Notes:

- Mark \checkmark for correct or minor mistake which does not require correction Mark \times for minor mistake that requires minor correction.

 Mark \times for major mistake that requires correction by replacement or re-fixing. Mark \times \times for major mistake that cannot be corrected.

 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7.	6.	5.	4.	3.	2.	1.	S No
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
	(((ζ,	(Quantitative Check (v or x)
	☐ Good ☐ Avg. ☐ Bad	☐ Good ☑ Avg. ☐ Bad	⊡ Good □ Avg. □ Bad	Good Avg. Bad	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	Good Avg. Bad	Qualitative Check (Good / Avg. / Bad)