Quality Control Check Repot.
uality Control Check
Control Check
Check

Stage: Before Casting Slab (Villas)

			The second of th
Slab No.	0/	SI. No.	8 1138 31129
Project	milair Estata	Phase	[2]
Sign	Sulders	Date	11/00/2018
) Sign	Minchestra	Date	11/08/2018
28489	Report filed and signed by PN	4?	Yes No
MD Sign		For filling	Yes No
port to QC team. Per submitting ATR	roceed only after recheck by Que on QC report to QC team. Inted out in the QC report. ATR	C. not required.	
	Block No 175 Slab No.	lock No 175 Slab No. 01 ompany wilgin estaty Project wilgin estaty epared by S. kaldelf Sign Sign revious stage report no. 2849 Report filed and signed by PN ecommendation: Stop further work. Submit ATR on QC report to QC team. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR Proceed with further work. ATR not required.	Project Sign Sign N\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\

Slab Check.

Notes:

- Inspection should be done before easting of slab at each stage i.e. when the slab is ready for easting.
 Prepare Slab Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
 Show length and width of balconies (Tolerance 1")
 Show inner dimensions of ducts. (Tolerance 1")
 Show location of sunken slab.

- Print an A3 size plan.
- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been easted.

 Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

Within tolerance of 14"?	Within tolerance of 1.4	\ - -	Actual:	4	Specified:	Staircase slab thickness
No No	Within tolerance of 12"? Yes No	1	Actual wd:	6.412	Specified wd: 6:41/2 Actual wd: 6:5"	Staircase width
Yes No	Within tolerance of 1279	1	Actual ht:	1	Specified ht:	Staircase - mid landing 2
S No	3.9 " Actual ht: 3.9" Within tolerance of 1/2"? Yes \No	3.911	Actual ht:	.ده غـ	Specified ht:	Staircase - mid landing1
		No	Ycs No	ii iiconicee	ed'?	Slab Dimensions Check Plan enclosed? Ves No

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	☐ Good ☐ Avg. ☐ Bad
18" extension to beam bottom runners on outer side provided?	☐ Yes ☑ No
Quality of Bracing Provided?	Good Avg. Bad
Alignment of beams on outer side?	Good Avg. Bad
Shuttering leveling?	Good Avg. Bad
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Correct Needs correction
Remarks:	

Slab Steel check.

Notes:

- Mark ✓ for correct or minor mistake which does not require correction

 Mark X for minor mistake that requires minor correction.

 Mark X X for major mistake that requires correction by replacement or re-fixing.

 Mark X X for major mistake that cannot be corrected.

 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

S No	Item	Quantitative Check	Qualitative Check (Good / Avg. / Bad)
	Steel Check - Beam no of rods	•	☐ Good ☐ Avg. ☐ Bad
2.	Steel Check - Beam size of bars	<	☑ Good ☐ Avg. ☐ Bad
3.	Steel Check - Beams Extra Bars	<	☐ Good ☑ Avg. ☐ Bad
4.	Steel Check - Beams Overlapping & Cranking	<	☐ Good ☐ Avg. ☐ Bad
5.	Steel Check - Beams Bearing	ζ	☐ Good ☑ Avg. ☐ Bad
6.	Covering blocks for beams	<	Good Avg. Bad
7.	Depth and width of beams		Good Avg. Bad
8.	Steel Check - Slab size of bars	<	☐ Good ☐ Avg. ☐ Bad
9.	Steel Check - Slab spacing of bars	•	☐ Good ☑ Avg. ☐ Bad
10.	Steel Check · Slab cranking & chairs		☐ Good ☑ Avg. ☐ Bad
	Steel Check - Slab Extra Bars		☐Good Avg. ☐ Bad
ני	Covering blocks for slab		Good Avg. Bad
13.	Steel Check - Column steel overlapping length and	•	Good Avg. Bad
14.	Electrical Conducting		Good Avg. Bad
15.	Steel check floating columns		Good Avg. Bad
16.	Steel check slab extensions joints	<	Good Avg. Bad
Remarks			