## Quality Control Check Repot. Stage: After Plastering (Villas)

Villa No.	. 18	Stage	٠	SI. No.	33030
Company	SOV (CLP)	Project	702	Phase	(~)
Prepared by	S. Kuldup	Sign	A) Cuttery	Date	27/02/19
Project Manager	K. Purshatham Sign	Sign	F	Date	27/02/18
Previous stage report no.	t no.	32649	Report filed and signed by PM?	d by PM?	Yes No
Checked By MD on		MD Sign		For filling	□ Yes □ No
Recommendation: Stop further work Stop further work Proceed with furt Proceed with furt	Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.	port to QC team. Proceer submitting ATR or ing corrections pointeired.	seed only after recheck l QC report to QC team d out in the QC report.	by QC.  ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

## Plastering Check.

Notes:

- Mark  $\checkmark$  for correct or minor mistake which does not require correction Mark  $\times$  for minor mistake that requires minor correction.

  Mark  $\times \times$  for major mistake that requires correction by replacement or re-fixing. Mark  $\times \times \times$  for major mistake that cannot be corrected.

  9"unplastered area from SFL should be left including in common areas and terraces.
- Windows must be checked with templates. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

## Quality Control Check Repot. Stage: After Plastering (Villas)

Trige Cilcul	
Overall quality of plastering?	Good Avg. Bad
Plastering of compound wall & gate pillars ( v or x)	
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	Yes No
Plastering quality of paranet walls ( v or v)	
	7
Plastering and finishing of chajjas ( v or x)	<
Remarks:	