Quality Control Check Repot. Stage: After Plastering (Villas)

Recommendation:	Villa No. Company Prepared by Project Manager Previous stage report no. Checked By MD on Recommendation:	208 voi(UP) S. Kuldeer A. awesh.	Stage Project Sign Sign Sign 31746 MD Sign	Phase Phase Phase Date Report filed and signed by PM?	S1. No. Phase Date Date d by PM? For filling	30/01/19 30/01/19 27es []No
MD Sign For filling	Previous stage report	no.	31716	Report filed and signe	d by PM?	Yes No
	Checked By MD on		MD Sign		For filling	☐Yes ☐No

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check,

Notes:

- Mark v for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or re-fixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance 1/2".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have "grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

Quality Control Check Repot. Stage: After Plastering (Villas)

MISCEllaneous check	
Overall quality of plastering?	Good Avg. Bad
Plastering of compound wall & gate pillars (or x)	×
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	Yes No
Plastering quality of parapet walls (✓ or 🗙)	
Plastering and finishing of chajjas (✓ or 🗙)	
Remarks:	