## Quality Control Check Repot. Stage: After Plastering (Villas)

Villa No.  262  Stage  Company  Company	Recommendation:  Stop further work. Submit ATR on QC report Stop further work. Proceed with work after some Proceed with further work only after making Proceed with further work. ATR not required	Checked By MD on		Project Manager A. SURESH	Prepared by ( AASE SH !	Company \\ \( \lambda \cappa \) \( \lambda \cappa \) \\ \( \lambda \cappa \cappa \cappa \) \\ \( \lambda \cappa	Villa No. 252
SI. No.  Phase  Phase  Date  Report filed and signed by PM?  Red only after recheck by QC.  QC report to QC team.  QC report. ATR not required.	oort to QC team. Proce er submitting ATR on ng corrections pointed red.	MD Sign	33130	Sign	Sign	Project	Stage
Sl. No.  Phase  Date  Date  Date  d by PM?  For filling  by QC.  ATR not required.	ed only after recheck l QC report to QC team l out in the QC report.		Report filed and signe	J.W	ehr.	Voc	1
	by QC. ATR not required.	For filling	d by PM?	Date	Date	Phase	SI. No.

### Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

#### Plastering Check.

#### Notes:

- Mark ✓ for correct or minor mistake which does not require correction
- Mark X for minor mistake that requires minor correction.

  Mark XX for major mistake that requires correction by replacement or re-fixing.

  Mark XX for major mistake that cannot be corrected.

  9"unplastered area from SFL should be left including in common areas and terraces.

- Windows must be checked with templates. Tolerance ¼". Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have 1/2" grooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges.

S No

Room

Skirting Provision

frame ( v or X)

Beams & columns

finishing ( v or x)

Finishing of lofts

Electrical junctions

finishing ( v or X)

Window check

Tiles provision

Sink provision & size

Balcony & terrace sill top finishing 10 ( or X)

Screeding in bathroom & utility ( or X)

Screeding in 6" above FFL? (v or x)

Grooves for door

frames ( v or x)

( ✓ or X)

( **v** or **X**)

( v or X)

( ✓ or X)

Finishing around door

( v or X)

1

1

1

14 13

Terrace/balcony 2

Terrace./ balcony l

18 17 16 15

Utility Kitchen

Portico

Head room

19

Other

10

Lobby i

Labby 2

Drawing

Toilet 4 Bedroom 4 Toilet 3

Toilet 2

Bedroom 2

Bedroom 3

Toilet 1

Bedroom 1

84 · 65

# Quality Control Check Repot. Stage: After Plastering (Villas)

IVIIscellaneous check	0
Overall quality of plastering?	Good WAvg. Bad
Plastering of compound wall & gate pillars ( v or x)	. ×
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	Yes No
Plastering quality of parapet walls ( v or x)	
Plastering and finishing of chajjas ( v or x)	
Remarks:	