Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Previous stage report no. 31930 Report filed and signed by PM?  Checked By MD on MD Sign For filling
T no. 31930 Report filed and signe MD Sign
MD Sign

## Plinth Beam Check.

Notes:

- Inspection should be done before casting of plinth beam.

  Yellow enamel paint to be used for marking FFL of flooring. Mark 2" above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark. Prepare plinth beam. Dimensions Check Plan as follows:

- Show outer dimensions. (Tolerance 2")
  Show length and width of plinth beams (Tolerance 1")
- Print an A3 size plan.
- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

  Project managers must make pedestal/column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.

Plinth Beam Dimensions Check Plan enclosed?	
Yes No	

## Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	☐ Good Avg. ☐ Bad
Have rods for staircase slab been provided?	Yes No
Quality of Bracing Provided?	☐ Good []/Avg, ☐ Bad
Alignment of beams on outer side?	☐ Good ☐ Avg. ☐ Bad
Brackets for elevation features provided?	☐Yes ☐No ☐NA
Level marking at 2' above FFL is made?	Yes No
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	☐ Correct ☐ Needs correction
Pedestal/column0 – self check report attached?	∑Yes □ No
Remarks: were contains work way poor need to be in	he impossued.

## Plinth Beam Steel check.

Notes:

- Mark v for correct or minor mistake which does not require correction

  Mark x for minor mistake that requires minor correction.

  Mark x x for major mistake that requires correction by replacement or re-fixing.

  Mark x x for major mistake that cannot be corrected.

  Columns overlapping length should be 45 to 50 D.

## Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7. Depth and width of beams	6. Covering blocks for beams	5. Steel Check - Beams Bearing	4. Steel Check - I	3. Steel Check - I	2. Steel Check - I	1. Steel Check - 1	S No
	th of beams	ks for beams	Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	Item
	<	ζ.	ς	7	7	<	7	Quantitative Check ( • or ×)
	☐ Good ☐ Avg. ☐ Bad	Good Avg. Bad	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	☑ Good ☐ Avg. ☐ Bad	☐ Good ☐ Avg. ☐ Bad	Qualitative Check (Good / Avg. / Bad)