Ouality Co
V Control
ty Control Check Repot.
Stage: Before Casting S
g Slab (Villas)

Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.	Checked By MD on	Previous stage report no.	Project Manager A.Susush	Prepared by S. Kuldeep	Company you (LLP)	Block No 286
QC team. Panitting ATR rections poir	MD Sign	31592	Sign	Sign	Project	Slab No.
Recommendation:  Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR pot required.		Report filed and signed by PM?		Support	VOC	710
C. not required.	For filling	M?	Date	Date	Phase	SI. No.
	Yes No	Yes' No	8190 001 (41	17/10/2018		31785

## Slab Check.

Notes:

- 1. Inspection should be done before casting of slab at each stage i.e. when the slab is ready for casting.

- Prepare Slab Dimensions Check Plan as follows:

  a. Show outer dimensions of slab. (Tolerance 2")

  b. Show length and width of balconies (Tolerance 1")
- Show inner dimensions of ducts. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.
- 7 in Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted. Circle each correct dimension with red colour and mention actual dimension next to it.

Slab Dimensions Check Plan enclosed?	d?		∠Yes □ No	No		
Staircase - mid landing1	Specified ht:	2-0-	Actual ht:	1.36.	2'.0" Actual ht: 1'9' Within tolerance of 1/2"? Tycs \( \subsection \) No	√Ycs □No
Staircase - mid landing 2	Specified ht:	1	Actual ht:	-	Within tolerance of 1/2"?	☐ Yes ☐ No
Staircase width	Specified wd: 6'b" Actual wd: 6'6"	478	Actual wd:		Within tolerance of ½"? ☑Yes ☐No	☐Yes ☐No
Staircase slab thickness	Specified:	ωĩ	5" Actual: 5"	OT W	Within tolerance of 1/4"?	√Yes □No
		•				

## Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Quality of centering, rod bending and concreting.	
Quality of centering, rod bending and concreting?	☐ Good ☑ Avg. ☐ Bad
18"extension to beam bottom runners on outer side provided?	□Yes ☑No
Quality of Bracing Provided?	Good ☐ Avg. ☐ Bad
Alignment of beams on outer side?	Good ☐ Avg. ☐ Bad
Shuttering leveling?	☐ Good ☑ Avg. ☐ Bad
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Correct Needs correction
Remarks: NOTE: Quality of Rod binding work ha	ham to be
implemed.	

## Slab Steel check. Notes:

- Mark o for correct or minor mistake which does not require correction
   Mark X for minor mistake that requires minor correction.
   Mark X for major mistake that requires correction by replacement or re-fixing.
   Mark X X for major mistake that cannot be corrected.
   Columns overlapping length should be 45 to 50 D.

## Quality Control Check Repot. Stage: Before Casting Slab (Villas)

			Remarks:
Good Avg. Bad	en de la companya de	Steel check - slab extensions/ joints	16.
Good Avg. Bad	(	Steel check – floating columns	15.
Good Avg. Bad	•	Electrical Conducting	14.
☐Good ☐ Avg. ☐ Bad	<	Steel Check - Column steel overlapping length and cranking	13.
☐ Good ☑ Avg. ☐ Bad	<	Covering blocks for slab	12.
☐ Good ☐ Avg. ☐ Bad		Steel Check - Slab Extra Bars	11.
☐ Good ☐ Avg. ☐ Bad	<	Steel Check - Slab cranking & chairs	10.
☐ Good ☑ Avg. ☐ Bad	<	Steel Check - Slab spacing of bars	9.
☐ Good [Avg. ☐ Bad	7	Steel Check - Slab size of bars	œ.
☐Good ☐ Avg. ☐ Bad	7	Depth and width of beams	7.
☐ Good ☐ Avg. ☐ Bad		Covering blocks for beams	6.
☐ Good ☑ Avg. ☐ Bad		Steel Check - Beams Bearing	5.
☐ Good ☐ Avg. ☐ Bad		Steel Check - Beams Overlapping & Cranking	4.
Good Avg. Bad		Steel Check - Beams Extra Bars	3.
☐Good ☐Avg. ☐Bad	<	Steel Check - Beam size of bars	2.
Good Avg. Bad	<	Steel Check - Beam no of rods	1,
Qualitative Check (Good / Avg. / Bad)	Quantitative Check ( < or ×)	Item	S No