Quality Control Check Repot. Stage: After Plastering (Villas)

Villa No		Starre		CI NI	
	52	2800		51. INU.	305(6
Company	MRM(UP)	Project	AMH	Phase	
Prepared by	M-Teja Sin dhu Sign	Sign	1	Date	13/06/18
Project Manager	Vukat Roo Sign	Sign	Mal	Date	13/06/18
Previous stage report no.	no.	30269	Report filed and signed by PM?	ed by PM?	Nes No
Checked By MD on		MD Sign		For filling	☐ Yes ☐ No
Recommendation: Stop further work. Stop further work. Proceed with furth Proceed with furth	Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.	port to QC team. Procer submitting ATR on ing corrections pointedired.		k by QC. m. t. ATR not required.	

Inspection should be done after:

- brickwork & 2 coats plastering is completed
- after cleaning the Villa.
- water proofing, screeding in bathrooms is completed.
- before starting painting, tiling & flooring.

Plastering Check.

- Mark ✓ for correct or minor mistake which does not require correction.

 Mark X for minor mistake that requires minor correction.
- Mark XX for major mistake that requires correction by replacement or rc-lixing.
- Mark XXX for major mistake that cannot be corrected.
- 9"unplastered area from SFL should be left including in common areas and terraces. Windows must be checked with templates. Tolerance ¼".
- Provision of tiles in bathrooms, kitchen & wash areas (rough plastering). Check size of sink bowl. Hole should be 1" to 2" larger. (Tolerance: 1")
- All doors frames should have langrooves.
- Sill top must be of uniform thickness, correct height, at one level & without broken edges,

Ren	19	18	17	16	15	14	13	12	1	10	9	~	7	6	رن ،		. L	2	—	S No
Remarks XX frushung	Other	Utility	Kitchen	Portiee-	Head reom	Texace/balcony 2	Terracc + baleeny-1	Lobby 2	-Lobby 1 Prowwy 11	Dining	Drawing	Toilet 4 (CT)G	Bedroom 4 (4,6)4	Toilet 3 (MT)4.4	Bedroom 3 (Mek.	Toilet 2 (KT)U+	m 2(K6)	Toilet 1 (MT)UT	Bedroom 1(MB)UT	Room
more			<	1	1	1	}	Ĩ	\ <	Z	<	Ž	<	<	Z	<	<	<	<	Skirting Provision (• or ×)
new			1	1	1	1	,	1]	1	<	<	<	<	<	<	<	<	<	Finishing around door frame (• or ×)
Windows			\	1	1	1		1	<	<	<	4	<	<	<	<	<	ς΄	<	Beams & columns finishing (v or x)
ous in			<	(1	١	1	1	\	Ţ]	t	1	ſ	١	ı	j	1)	Finishing of lofts (• or ×)
3			<	[1	[}	}	<	<	ς	۷	<	<	<	V	<	く	<	Electrical junctions finishing (v or x)
•			<	J	[1	1		<	1	<	<	5	<	火火	<	<	<	<	Window check (✓ or X)
Bedroom			<	1]	1		1	1	1	5	~	.1	<	١	<	1	۲	}	Tiles provision (✓ or X)
(G.L			<	1	1	1	1	1	1	1	J	<	1	<	١		1	<	1	Sink provision & size (v or x)
(वर्ष)			1	\	1)))		/		<	<	<	٢	70	X,	×	`	Grooves for door frames (• or ×)
767			1	(1	1	1	1		1)	\	1	(•	1)]	j	Balcony & terrace sill top finishing 10 (v or x)
don			,			1)))	((1	1	1	1	<	J	Screeding in bathroom & utility (v or x)
				1	١	})			1		\	1	,	J	`\)	۲)	Screeding in 6" above FFL? (v or x)

Quality Control Check Repot. Stage: After Plastering (Villas)

Miscellaneous check	
Overall quality of plastering?	Good WAve. Bad
Plastering of compound wall & gate pillars (v or x)	
Is plastering of compound wall and villa external walls 6" below FFL of setbacks?	TYes Nivo
Plastering quality of parapet walls (or x)	
Plastering and finishing of chajjas (v or x)	
Remarks:	*