Quality Control CI
ieck Repot.
Stage: Before Casting Slab (Villas)
asting Slab (Vil

Stop further work. S Stop further work. I Proceed with further	Pagement 1.	Cholind Balving report no.	Previous store report	Project Manager	Prepared hy	Company	ー スニングマンニン
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck less than the work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.			sala musialitizishna	V. Sanketh	523	50	500000
QC team. Pr nitting ATR rections poin	MD Sign	33393	Sign	Sign	Project	Slab No.	200 A 100 A 100 A
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.		Report filed and signed by PM?	( Panul	1. Butuch	Blamchale	02	
not required.	For filling	[?	Date	Date	Phase	Sl. No.	
	☐Yes ☐No	Yes No	20/05/19	20 05/19	1	33622	

## Slab Check.

Notes:

- 1. Inspection should be done before casting of slab at each stage i.e. when the slab is ready for casting.
- Prepare Slab Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconics (Tolerance 1") Show inner dimensions of ducts. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.
- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension

Slab Dimensions Check Plan enclosed?       Image: Color and mention actual dimension next to it.         Staircase - mid landing 1       Specified ht: 3-0" Actual ht: 3-0" Within tolerance of ½"?       Within tolerance of ½"?       Wyes □ No         Staircase width       Specified wd: 5" Actual wd: 5" Actual wd: 5" Within tolerance of ½"?       Within tolerance of ½"?       Yes □ No         Staircase slab thickness       Specified: 5" Actual: 5" Within tolerance of ½"?       Yes □ No							
Plan enclosed?    Specified ht: 3-c"   Actual ht: 3-c"   Within tolerance of ½"?   Specified wd:   Actual wd:   Within tolerance of ½"?	√Yes □ No	- 1	ហ្ម	Actual:	יל ב	Specified:	Stan Case Slab Unickness
In enclosed?    Specified ht: 3-0"   Actual ht: 3-0"   Within tolerance of ½"?   Specified ht: 5-3"   Actual ht: 5-3"   Within tolerance of ½"?	☐Yes ☐No	Within tolerance of 1/2"?		Actual wd:	•	Specified wd:	Staircase width
lan enclosed?	Yes No		5-3"	Actual ht:	5-3	Specified ht:	Staircase - inid landing Z
Plan enclosed? Yes No	Yes No		3-0"	Actual ht:		Specified ht:	Staircoan mid 1 - 1: 2
Yes No					- 1	0 11	Staircase - mid landing!
	0 If.	mention actual dimension next to	No No	Yes		;b;	Slab Dimensions Check Plan enclose

## Quality Control Check Repot. Stage: Before Casting Slab (Villas)

			Remarks:	Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Shuttering leveling?	Auguilett of deams on outer side?	Alignment of board 10010e07	Onality of Brooks Brooks 19	Quanty of centering, rod bending and concreting?	Quality of centering, rod bending and concreting.
				✓ Correct Needs correction	Good Avg. Bad	✓Good Avg. Bad	☐ Good ☑ Avg. ☐ Bad	☐ Yes ☑ No	☐ Good ✓ Avg. ☐ Bad	

## Slab Steel check.

Notes:

- Mark v for correct or minor mistake which does not require correction
   Mark X for minor mistake that requires minor correction.
   Mark X for major mistake that requires correction by replacement or re-fixing.
   Mark X X for major mistake that cannot be corrected.
   Columns overlapping length should be 45 to 50 D.

## Quality Control Check Repot. Stage

	ot.
	Stage
200	Stage: Before Casting Slal
	e Castin
	ng Slab
	(Villas)

			Remarks:
Good Avg. Bad	1	Steel check – slab extensions/joints	16.
Good Avg. Bad	1	Steel check – floating columns	15.
Good Avg. Bad	~	Electrical Conducting	14.
Good Avg. Bad	<	cranking	10.
Good Avg. Bad	<	Covering blocks for slab	12.
ସ Good ☐ Avg. ☐ Bad	<	Steel Check - Slab Extra Bars	13 11.
Good Avg. Bad	< <	Steel Check - Slab cranking & chairs	10.
⊡ Good √Avg. ☐ Bad	<	Steel Check - Slab spacing of bars	9.
✓ Good ☐ Avg. ☐ Bad	<	Steel Check - Slab size of bars	
☐Good☐Avg.☐Bad	<	Depin and width of beams	0 .
☐ Good ☑ Avg. ☐ Bad	<	Covering blocks for beams	7 0.
☑ Good ☐ Avg. ☐ Bad	<	Steet Check - Beams Bearing	, .
⊡ Good ☑ Avg. ☐ Bad	4	Steel Check - Beams Overlapping & Cranking	, t
✓ Good Avg. Bad	V	Steel Check - Beams Extra Bars	۷ .
☑ Good ☐ Avg. ☐ Bad	<	Steel Cncck - Beam size of bars	2 1
V Good Avg. Bad	<	Steel Check - Beam no of rods	<b>3</b>
Qualitative Check (Good / Avg / Rad)	Quantitative Check ( • or ×)	TICIL	a !
	>	Itam	SNo