Quality Control Check Repo	
t. Stage; After Column C	
Casting (villas)	

Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Froject Manager Bulo mus	S. Kulder	Premared by KNM	Company 52	
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not proceed with further work.	MD Sign	31380	Bulo mulableishy Sign	Les Sign	2 Project	Column No.	
ceed only after recheck b n QC report to QC team. ed out in the QC report. A		Report filed and signed by	Caron	- Compander	Bloomdale	20	
y QC. .TR not required.	For filling	d by PM?	Date	Date	Phase	SI. No.	
	Yes No	Yes No	24/09/2010	24 09 2018	***************************************	05518	2

Notes:

- Inspection should be done after casting of columns at each stage and before starting centering works for each slab.
 Prepare Columns Position Check Plan as follows:
- Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5") Show inner inner space between columns. (Tolerance 1")
- Show diagonals for 20% of bays. (Tolerance 1.5")
- Print an A3 size plan.

Slab Dimensions Check	Columns Position Check Plan enclosed?
	ncorrect dimension with red colour and mention actual dimension next to it. Yes No

Notes:

- 1. Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")
- Show inner dimensions of ducts and lift well. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.
- Sis Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dir

Specified thickness of slab?	Slab Dimensions Check Plan enclosed?
Actual thickness of slab?	Yes No

Quality Control Check Repot. Stage: After Column Casting (villas)

Quality of centering, rod bending and concreting.		Good Avg. Bad
Quality of starters?		☐Good ☐ Avg. ☐ Bad
Number and size of honey combs?		☐ High ☐ Medium. ☐ Low
Are the honey combs is slab and columns packed?		☐ Good ☑ Avg. ☐ Bad
Number of beams that are sagging, bulging, caved or deflected in the slab by more than 1".	than 1"	1
Have 6 cubes each for columns and slab casted and numbered for testing?		☐Yes ☐ No
Remarks:		
Bunds for curing made on slab?	Yes No	
Bund size is less than 100 sft?	☐Yes ☐ No	
Drum (200 lts) provided for curing?	Yes No	
Gunny bags used for column curing?	Yes No	
Distance of tap from furthest distance that requires curing. (max permitted 100')	20'-0"	
Frequency of curing in number of times a day (enquire from labourers)	2 times	
Is the pressure in the curing pipe more than 15' head?	☐Yes ☐No	
Quality of infrastructure for curing.	Good MAvg.	Bad
Remarks:		

Columns height, plumb, steel & level marking check.

Notes:

- Mark v for correct or minor mistake which does not require correction
 Mark x for minor mistake that requires minor correction.
 Mark x for major mistake that requires correction by replacement or re-fixing.
 Mark x x for major mistake that cannot be corrected.
 Tolerance: Plumb 0.25".

Circle actual height of columns if level differs from specified height by more than 1".

No Col No. Col type Height in ft Steel (or x)

ON NO	Col No.	Cot type	Heig Spec.	Height in It		⊣′ر	Honeycombs	ombs	
			spec.	Actual	rods	Size of rods			Side I
) -	Ð,	CH	8'. 7'2"	##- (B)	<u></u>	ς		7	7
۲.	Az	62	81-410"	14-18	ζ	7		<	
۷ .	± NZ	(3	p'-1%"	81-211	7	<		7	
λ .‡	AR	47	1,34-18	81.81	<	7		<	<
٠.	23	63	8-71/2"	81-81	ξ.	<		<	
1 0	BL	62	18/2 1/8	31-01	ς	`		ć	c c
0 /	Вч	CZ	12/4-18	8-8"	<	(ζ	
9 9	BC	52	11/14-18	81-81	((?	(
7.	C3	(3	8-4/2	8-7/2"	ζ.	7		ς.	< _
10.	D S	5	8 4/2"	81-2611	?	ζ		ζ.	(
	م	Co	81-1/21	· 8), 111	(>			
12.	4	ez	8/1/2/	B* 211	<	(-		
13.	4	CA	82 3/21	8)_#"	ζ.	ζ.		ζ,	
14.	CF	Cy	81,11/2"	8/2"	<	ς .		(<
16	62	1)	8/21/2"	8-81	2	2		((
17									
18									
19.									
20.							le:		