Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.	Checked By MD on	Previous stage report no.	Prepared by Project Manager Project Manager		Company 5	Block No
	MD Sign	30692		P. Sis Kunner	SONCLLP)	64
			Sign	Sign	Project	1
		Report filed and signed by PM?	K	200	SOV	
	For filling	ed by PM?	Date	Date	Phase	Sl. No.
	☐ Yes ☐ No	UYes □No	1/12/18	1112/18	X	32257

Quality Control Check Repot.

Stage: Before Casting Plinth Beam (Villas)

Plinth Beam Check.

Notes:

- Inspection should be done before casting of plinth beam.

 Yellow enamel paint to be used for marking FFL of flooring. Mark 2' above FFL on column steel. Plinth beam top must be 2'3" (in case of pavers) or 2'4" (in case of RCC slab) below the mark. Prepare plinth beam Dimensions Check Plan as follows:

 a. Show outer dimensions. (Tolerance 2")

 b. Show length and width of plinth beams (Tolerance 1")
- Print an A3 size plan
- Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension next to it.

 Project managers must make pedestal/column 0 self check report similar to report for column check. QC must collect report and attach the same to this report.

Plinth Beam Dimensions Check Plan enclosed?	Yes No
COLUMN SO ACCUSE TO THE AND COLUMN SOUND S	

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Quality of centering, rod bending and concreting. Quality of centering, rod bending and concreting? Have rods for staircase slab been provided?	☐ Good Āvg. ☐ Bad
Quality of Bracing Provided? Alignment of beams on outer side?	☐ Good ☑ Avg. ☐ Bad
Brackets for elevation features provided?	□Yes □No ☑ÑA
Level marking at 2' above FFL is made?	☐ Yes ☐ No
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	Correct Needs correction
Pedestal/column0 – self check report attached?	☐ Yes ☐ No
Remarks:	

Plinth Beam Steel check.

Notes:

- Mark v for correct or minor mistake which does not require correction Mark x for minor mistake that requires minor correction.

 Mark x for major mistake that requires correction by replacement or re-fixing. Mark x x for major mistake that cannot be corrected.

 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stage: Before Casting Plinth Beam (Villas)

Remarks:	7.	6.	5.	4.	3.	2.		S No
	Depth and width of beams	Covering blocks for beams	Steel Check - Beams Bearing	Steel Check - Beams Overlapping & Cranking	Steel Check - Beams Extra Bars	Steel Check - Beam size of bars	Steel Check - Beam no of rods	ltem
<	<.	C	<	<	<		(v or X)	Quantitative Check
Avg. Bad	Good Avg. Bad	☐ Good ☐ Avg. ☐ Bad	Good Avg. Bad	✓ Good Maye. Bad	Wood Avg. Bad	M Good Avg. Bad	(Good / Avg. / Bad)	Oualitative Check