Recommendation: Stop further wo Stop further wo Proceed with fi	Checked By MD on	Previous st	Project Manager	Prepared by	Company	Block No
dation: ther work. Sther work. with furthe with furthe	y MD on	Previous stage report no.				
Recommendation: Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck b Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. Proceed with further work. ATR not required.		0.	A. Swest	V. Sanketh	YOC CLLP)	65
to QC team. Pr bmitting ATR orrections poir	MD Sign	31469	Sign	Sign	Project	Slab No.
Stop further work. Submit ATR on QC report to QC team. Proceed only after recheck by QC. Stop further work. Proceed with work after submitting ATR on QC report to QC team. Proceed with further work only after making corrections pointed out in the QC report. ATR not required. Proceed with further work. ATR not required.		Report filed and signed by PM?		V. Sunkut	70C	G
C.	For filling	Л ?	Date	Date	Phase	SI. No.
	☐Yes ☐No	Yes No	25-09-18	25-09-18		31548

Quality Control Check Repot.

Stage: Before Casting Slab (Villas)

Slab Check.

Notes:

- Inspection should be done before casting of slab at each stage i.e. when the slab is ready for casting.
- Prepare Slab Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")
- Show inner dimensions of ducts. (Tolerance 1")
- Show location of sunken slab.
- Print an A3 size plan.
- Mid landing height is no. of risers x riser height. Measure from SFL to SFL. Check staircase of lower floor that has been casted. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention actual dimension

Slab Dimensions Check Plan enclosed?	:d?		✓ Yes □No		
Staircase - mid landing1	Specified ht:	-	Actual ht:	Within tolerance of 1/2"?	☐Yes ☐No
Staircase - mid landing 2	Specified ht:	1	Actual ht:	Within tolerance of 1/2"?	☐Yes ☐No
Staircase width	Specified wd:	, A	Actual wd:	Within tolerance of 1/2"?	☐Yes ☐No
Staircase slab thickness	Specified:	A	Actual:	Within tolerance of 1/4"?	☐Yes ☐No

Quality Control Check Repot. Stage: Before Casting Slab (Villas)

Quality of centering, rod bending and concreting. Quality of centering, rod bending and concreting? 18"extension to beam bottom runners on outer side provided? Quality of Bracing Provided? Alignment of beams on outer side? Shuttering leveling? Column steel overlapping and cranking? (overlapping length should be 45 to 50 D) Remarks:	Good Avg. Bad Yes No Good Avg. Bad Good Avg. Bad Good Avg. Bad Good Avg. Bad Correct Needs correction
Column steel overlapping and cranking? (overlapping length should be 45 to 50 D)	☑ Correct ☐ Needs correction
Remarks:	

Slab Steel check.

Notes:

- Mark v for correct or minor mistake which does not require correction
 Mark x for minor mistake that requires minor correction.
 Mark x for major mistake that requires correction by replacement or re-fixing.
 Mark x x for major mistake that cannot be corrected.
 Columns overlapping length should be 45 to 50 D.

Quality Control Check Repot. Stuge: Before Casting Slab (Villas)