Quality Control Check Repot. Stage: After Column Casting (villas)

					-			
Columns Position Check	Stop further work. Submit A1K on QC report  Stop further work. Proceed with work after su  Proceed with further work only after making of the proceed with further work. ATR not required.	Recommendation:	Checked By MD on	Previous stage report no.	Project Manager	Prepared by	Сотрапу	Block No.
<del>3.</del>	Proceed with work aff ar work only after mak ar work. ATR not requ			0.	A. Swesh Sign	V. Sandett Sign	VOCCLP) Project	29
	ired.		MD Sign	30752	Sign	Sign	Project	Column No.
• 30	Stop further work. Submit ATK on QC report to QC team, Proceed only after recneck by QC.  Stop further work. Proceed with work after submitting ATR on QC report to QC team.  Proceed with further work only after making corrections pointed out in the QC report. ATR not required.  Proceed with further work. ATR not required.			Report filed and signed by PM?	( <del>)</del>	V. EMAD	YOC	02
	ATR not required.		For filling	ed by PM?	Date	Date	Phase	SI. No.
•			Yes No	☐Yes ☐ No	81-to-61	81-40-61		30868

Notes:

- Inspection should be done after easting of columns at each stage and before starting centering works for each slab.
- Prepare Columns Position Check Plan as follows:
- Divide blocks into smaller sub-blocks.
- Show size and orientation of columns. (Tolerance 0.5")
- Show inner inner space between columns. (Tolerance 1")
- Show diagonals for 20% of bays. (Tolerance 1.5")
- Print an A3 size plan.

က	3.
olumns Position Check Plan enclosed?	3. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention ac
√Yes □No	tual o
	Yes No

## Slab Dimensions Check.

- Prepare Slab (or plinth beams) Dimensions Check Plan as follows:
- Show outer dimensions of slab. (Tolerance 2")
- Show length and width of balconies (Tolerance 1")
  Show inner dimensions of ducts and lift well. (Tolerance 1")
- မ်ာ ပေ မှာ Show location of sunken slab.
- Print an A3 size plan.

Slab Dimensions Check Plan enclosed?	2. Circle each correct dimension with green colour. Circle each incorrect dimension with red colour and mention a
⊠Yes □ No	dimension with red colour and mention actual dimension next to it.

## Quality Control Check Repot. Stage: After Column Casting (villas)

Quality of centering, rod bending and concreting?		Tood Ava Bad
Quality of starters?		☐ Good ☑ Avg. ☐ Bad
Number and size of honey combs?		☐ High ☐ Medium. ☑ Low
Are the honey combs is slab and columns packed?		☐ Good ☐ Avg. ☐ Bad
Number of beams that are sagging, bulging, caved or deflected in the slab by more than 1"	than 1"	
Have 6 cubes each for columns and slab casted and numbered for testing?		√ Yes □ No
Remarks:		
Bunds for curing made on slab?	√Yes · No	ì
Bund size is less than 100 sft?	√Yes □No	
Drum (200 lts) provided for curing?	☐Yes ☑No	
Gunny bags used for column curing?	Yes No	
Distance of tap from furthest distance that requires curing. (max permitted 100')	30	
Frequency of curing in number of times a day (enquire from labourers)	2 times	
Is the pressure in the curing pipe more than 15' head?	Yes No	
Quality of infrastructure for curing.	√Good   Avg. [	Bad
Remarks:		

## Columns height, plumb, steel & level marking check. Notes:

Mark v for correct or minor mistake which does not require correction Mark X for minor mistake that requires minor correction.

Mark XX for major mistake that requires correction by replacement or re-fixing.

Mark XX for major mistake that cannot be corrected.

Tolerance: Plumb 0.25".

Circle actual height of columns if level differs from specified height by more than 1".

1	20.	19.	18.	10	17	16	15.	14.	13.	12.	11.	10.	9.	2 2		: p	· :	÷	z ţu	2.	· :			S No
								•		لا	7_	0_	5	1.7	8	134	<i>5</i> 2.	7	PL	Ð,	P)			Col No.
									,	6	<u>C</u> -		50	5	-	C2.	ر ال	7	(2	£3	(1)			Col type
										8-4=	81	, K. S	11 5/8	11 4 18	Stairs	8'4"	8/4"	Stan's	1. E ,S	= 4 -8	8 4 =		Spec.	Heigh
			:							9'4"	8/211	8/1/2/	15/5	1/2/8	Shirs	81 7- N	11 15	Stams	8.8"	2 2 1	128		Actual	Height in ft
										<	۷	<	<	<	۷	<	Z	2	۷	۷	3	rods	No of	Steel (
										く	く	<	<	<	<	۷.	<	<	(	<	۷	rods	Size of	Stecl ( or x)
										L	4	<b>〈</b>	く	۷	<	<	4	<	\	4	<b>4</b>			Honeycombs
										4	<,	<	۲	く	J	۷	<	۷	a.	۷	Z		Side I	Plumb
										<	<	<	<	~	· \	۷.	<u> </u>	۷,	~	۷	۲		Side 2	Plumb ( or x)
		☐Yes ☐No	☐ Yes ☐ No	☐ Yes ☐ No	∐Yes ∐No			☐ Yes ☐ No	☐ Yes ☐ No	√Ycs No	√Yes No	✓ Yes ☐ No	√Yes □ No	✓ Yes ☐ No	✓ Yes □ No	✓ Yes □ No	√ Yes □ No	☑Yes □No	✓Yes □No	√Yes □No	¬Yes □No	column?	marked on	Reference level